DOI HS-800 382 PB 197 552

CHILD SEAT AND RESTRAINT SYSTEMS TEST RESULTS

APPENDIX D

THE UNIVERSITY OF MICHIGAN
HIGHWAY SAFETY RESEARCH INSTITUTE
HURON PARKWAY AND BAXTER ROAD
ANN ARBOR, MICHIGAN 48105

Final Report
October 1970
Volume I of III
Contract No. FH-11-6962

PREPARED FOR:

NATIONAL TECHNICAL INFORMATION SERVICE Springfield, Va. 22151

U.S. DEPARTMENT OF TRANSPORTATION
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
WASHINGTON, D.C. 20591



The contents of this report reflect the views of the Highway Safety Research Institute of The University of Michigan, which is responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the official views or policy of the Department of Transportation. This report does not constitute a standard, specification or regulation.

,

§

,

1 Report No.	2. Government Accessi	on No.	3. Recipient's Catalog I	No
	·			
4 Title and Subtitle			5. Report Date	
Child Seat and Restraint Systems Test Results Appendix D. Volume I.		5	October 31, 1970	
			6. Performing Organization Code	
7 Author(s)			8. Performing Organization Report No. Bio M-70-2	
D.H. Robbins, A.W. Henke, and				
9 Performing Organization Name and Address			10. Work Unit No.	
Highway Safety Research Institute				
The University of Michigan		11. Contract or Grant !	No.	
Huron Parkway and Baxter Road Ann Arbor, Michigan 48105		FH-11-6962		
· · · · · · · · · · · · · · · · · · ·			13. Type of Report and Period Covered	
12. Sponsoring Agency Name and Address			Final Report	
National Highway Safety Burea Department of Transportation		January 1, 1969- October 31, 1970		
Nassif Building		14. Sponsoring Agency		
Washington, D.C. 20591				
15 Supplementary Notes				
1				
16 Abstract				
This report contains the data records obtained in a test program studying the safety performance of child car seats and restraint systems. Included with each test result is an HSRI Summary Data Sheet, a copy of an oscillographic record of transducer data and high speed photographic documentation of occupant kinematics. In cases where the oscillographic record or the photographic documentation is missing, the data was not obtained.				
Life Key Words	18. Distribution Statement			
,				
•				
i				
	.	<u></u>		
19 Security Classif (of this (eport)	20. Security Classif.(of	this page)	21. No. of Pages	22. Price



TABLE OF CONTENTS

Table of Contents

Acknowledgements

Volume I. Test Nos. A-017 to A-095 (pages 1-125).

Volume II. Test Nos. A-096 to A-130 (pages 126-249).

Volume III. Test Nos. A-131 to A-182 (pages 250-374).

ACKNOWLEGMENTS

This research program was carried out by staff members of the Biosciences

Division of the Highway Safety Research Institute, The University of Michigan.

The program was under the direction of Drs. D. H. Robbins and V. L. Roberts.

The impact sled tests were carried out under the direction of Mr. A. W. Henke with the assistance of Messrs. M. L. Dunlap, R. E. Pontius, and J. S. Brindamour.

Mr. J. T. Figurski provided photographic assistance.

Test No:

A-017

Test Date:

30 January 1969

Restraint Code No:

C-3

Restraint Description:

General Motors Corp. Standard Seat

Dummy:

Doll

Sled Velocity:

16 mph

Sled G-level:

3 (8)

Impact Direction:

Forward facing

Dummy Attitude:

Sitting

Test Observation:

There was no observable damage to either the dummy or the restraint system. No gross excursion was observed.

Test No:

A-018

Test Date:

30 January 1969

Restraint Code No:

C-31

Restraint Description:

Sears Child's Auto Harness, small

Dummy:

Do11

Sled Velocity:

60 mph

Sled G-level:

3 (11)

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

There was no observable damage to the dummy or to the restraint system. No gross dummy motions were observed.



Test No:

A-020

Test Date:

14 February 1969

Restraint Code No:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

16 mph

Sled G-level:

5 (8)

Impact Direction:


Forward facing


Dummy Attitude:


Sitting

Test Observation:

There was no damage observed either to the dummy or to the restraint system. There were no gross motions observed.







Test No:

A-021

Test Date:

14 February 1969

Restraint Code:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

16 mph

Sled G-level:

4 (7)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

There was no damage observed either to the dummy or to the restraint system. No gross motions were observed.





Test No:

A-022

Test Date:

14 February 1969

Restraint Code No:

C-31

Restraint Description:

Sears harness, small

Dummy:

3 year

Sled Velocity:

16 mph

Sled G-level:

4 (7)

Impact Direction:

Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was observed to either the dummy or the restraint system. No gross motions were observed.





Test No:

A-023

Test Date:

14 February 1969

Restraint Code No:

C-3

Restraint Description:

General Motors Corp. Standard Seat

Dummy:

3 year

Sled Velocity:

16 mph

Sled G-level:

4 (7)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was observed either to the dummy or to the restraint system. The head and upper torso of the dummy were observed to pitch forward as the bottom of the child seat dug into the cushion of the adult seat on which it was mounted.





Test No:

A-024

Test Date:

14 February 1969

Restraint Code No:

C-38

Restraint Description:

Wards Harness No. 66B6053

Dummy:

3 year

Sled Velocity:

16 mph

Sled G-level:

4 (7)

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

No damage or gross motion were observed in this test.



Test No:

A-025

Test Date:

14 February 1969

Restraint Code No:

C-12

Restraint Description:

Five-Filer Brothers Bail Seat

Dummy:

3 year

Sled Velocity:

16 mph

Sled G-level:

4 (7)

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

Seat was observed to swing up; however, no damage or gross motions were observed.



Test No:

A-026

Test Date:

14 February 1969

Restraint Code No:

C-11

Restraint Description:

Five-Filer Brothers Hook Under Seat

Dummy:

3 year

Sled Velocity:

16 mph

Sled G-level:

4 (7)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

The tubular structure of the seat was observed to fold up as the impact occurred. The dummy was ejected from the seat and violently contacted the sled structure.





Test No:

A-040

Test Date:

11 March 1969

Restraint Code No:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

30 mph

Sled G-level:

15

Impac: Direction:

Forward facing

Dummy Attitude:

Sitting

Test Observation:

The observed motions of the dummy were minimal.

Test No:

A-041

Test Date:

17 March 1969

Restraint Code No:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

30 mph

Sled G-level:

15 (37)

Impact Direction:

Forward facing


Dummy Attitude:

Sitting

Test Observation:

The motions experienced by the dummy were minimal. Head and chest g loadings were quite high.





Test No:

A-042

Test Date:

17 March 1969

Restraint Code No:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

30 mph

Sled G-level:

15 (42)

Impact Direction:

Forward facing


Dummy Attitude:

Sitting

Test Observation:

The Tot-Guard was not located properly on the adult seat. Dummy motions were minimal, except that the left leg became detached from the torso of the dummy. Chest and head accelerometer readings were quite high.





Test No:

A-043

Test Date:

18 March 1969

Restraint Code No:

C-31

Restraint Description:

Small Sears Harness

Dummy:

3 year

Sled Velocity:

30 mph

Sled G-level:

15 (41)

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

No damage was observed to either the dummy or to the restraint system. However, the adult seat back was bent severely by the harness strap which is looped over it. The excursion experienced by the dummy was probably sufficient to allow contact with a vehicle interior.



Test No:

A-049

Test Date:

16 April 1969

Restraint Code No:

C-5

Restraint Description:

Sears Seat No. 5516

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

15 (26)

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

The head and chest of the dummy were observed to pitch forward over the lap belt and the head pitch down far enough to apparently contact the front of the adult seat.



Test No:

A-050

Test Date:

16 April 1969

Restraint Code No:

C-5

Restraint Description:

Sears Seat No. 5516

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18 (32)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was observed either to the dummy or to the restraint system. However, the head of the dummy experienced very high g loadings. The head of the dummy was observed to pitch forward through a large arc downward until it contacted the front of the adult seat on which the child's seat was mounted.





Test No:

A-051

Test Date:

16 April 1969

Restraint Code No:

C-14

Restraint Description:

International Seat, Model No. 4613

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18 (36)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

The dummy experienced no damage although the head loads were quite high. The seat was badly damaged in this test. The tubular structure collapsed and was bent severely. The padded rail in front of the dummy was bent. The cross piece to which the seat back was riveted was also bent and the crotch strap snap came loose. The excursion of the dummy was probably sufficient to allow contact with the interior of the vehicle.





Test No:

A-052

Test Date:

16 April 1969

Restraint Code No:

C-10

Restraint Description:

Century Seat, Model No. 4865

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

16 (36)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was observed to the dummy, but excursions in this test were probably sufficient to allow contact with the interior of the vehicle. The seat experienced severe damage due to the collapse of the rear support bars at the rivet holes.





Test A 052

Test No:

A-053

Test Date:

21 April 1969

Restraint Code No:

C-15

Restraint Description:

International Seat No. 4513

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18 (32)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

Both bail hooks on this seat were broken and became unattached from the back of the adult seat. The molded back of the child seat flexed allowing the chest belt to slide up and become disengaged. The upper torso and head of the dummy pitched forward over the padded rail at the front of the seat.





Test No:

A-054

Test Date:

21 April 1969

Restraint Code:

C-9

Restraint Description:

Century Seat No. 4865

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18 (28)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

The dummy head and chest were observed to pitch over the handrail on the child seat. The seat was damaged to some extent. The left-hand and right-hand bail hooks were bent and straightened out to 112°. Bending was also observed at the pivot pin slot. The integral chest strap on the child seat pulled slack sufficiently so that a fist would fit between the strap and the torso of the dummy. Originally one could insert four fingers side by side in between the dummy chest and the strap. It was also frayed where it had pulled through the buckle. The handrail stops were bent backwards 17° allowing the rail to sag along with the seat and the dummy.





Test No:

A-055

Test Date:

22 April 1969

Restraint Code No:

C-6

Restraint Description:

George B. Walker Safety Seat

Dummy:

3 year

Sled Velocity:

21 mph

Sled G-level:

16 (29)

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

The loadings experienced by the dummy were minimal, probably due to the fact that the excursions were so large that impact with the vehicle interior would be certain. The seat experienced considerable damage. The bail hooks were straightened out as they pulled over the adult seat back. The handrail was bent into an elliptical shape by the impact of the dummy torso. The integral lap belt slipped allowing the lower torso of the dummy to slide forward, apparently due to the belt slipping in the adjusting loop. The crotch strap buckle was bent where it was attached to the handrail. The handrail was buckled downward at the support point approximately two inches forward of the attachment to the seat back. The underside of the bail hooks picked up material from the top of the adult seat as they slipped over the seat back.





Test No:

A-056

Test Date:

22 April 1969

Restraint Code No:

C-21

Restraint Description:

Bunny Bear Seat No. 3505

Dummy:

3 year

Sled Velocity:

21 mph

Sled G-level:

16

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

The loadings experienced by the dummy were quite small, however, its excursion was sufficiently large to allow contact with the interior of any vehicle. The seat experienced considerable damage. The belly straps pulled loose at each end because the rivets pulled out. The one-eighth inch by five-eighth inch steel diagonal folding braces supporting the seat back structure collapsed on both sides. The dummy jackknifed and was nearly ejected. The dummy appeared to be restrained by the auxiliary nylon safety straps which are not part of the seat structure.





Test No:

A-057

Test Date:

23 April 1969

Restraint Code No:

C-16

Restraint Description:

Klippan Child Seat

Dummy:

3 year

Sled Velocity:

21 mph

Sled G-level:

16

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

Dummy motion was minimal and no damage was observed. The spring shock absorber was hadly deformed indicating that considerable energy was absorbed. The fiberglass shell of the seat was fractured at two points where the belts were attached. It was deformed at the rear upper seat restraining strap and also at the location of the right-hand lower restraining strap. The dummy was observed to rebound back into the child seat.





Test No:

A-058

Test Date:

28 April 1969

Restraint Code No:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

21 mph

Sled G-level:

16 (33)

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

No damage was observed either to the dummy or to the restraint system and motion was minimal.



Test No:

A-059

Test Date:

30 April 1969

Restraint Code No:

C-4

Restraint Description:

Sears Seat No. 28A6400C

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

16

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was observed either to the dummy or to the restraint system. However, the head g loading was quite high. The bottom of this pedestal type seat dug far into the adult seat cushion causing a considerable motion amplification of the upper torso and head of the dummy. The head of the dummy and that portion of the chest which was above the chest restraint strap pitched violently forward.





Test No:

A-060

Test Date:

1 May 1969

Restraint Code No:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

16

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

Seat belt loadings and accelometer readings for this test were comparable with other tests on this restraint system. No motion pictures were taken.



Test No:

A-067

Test Date:

8 May 1969

Restraint Code No:

C-18

Restraint Description:

Strolee Seat No. 587

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was observed to the dummy. However, due to the structural failure of the seat the dummy was ejected and violently contacted the interior of the body buck which was being used in this test. The under structure collapsed as the main tube on the right side of the seat broke at the rivet holes. The straps holding the child's seat to the adult seat held. The restraining strap hook on the child seat failed as the wire straighten and was lost. The handrail came loose.





Test No:

A-068

Test Date:

8 May 1969

Restraint Code No:

C-19

Restraint Description:

Strolee Seat No. 589

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:

Forward facing


Dummy Attitude:

Sitting

Test Observation:

The seat structure collapsed allowing the dummy to move forward and contact the body buck. The tubular structures supporting the seat cushion were completely buckled. The chest harness was torn at the lower right attachment point. The right-hand retaining strap of the child's seat was torn by the teeth of the buckle.





Test No:

A-071

Test Date:

16 May 1969

Restraint Code No.:

C-20

Restraint Description:

Bunny-Bear Seat T8905H

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

The loadings experienced by the dummy were quite low. However, the seat structure failed leading to very large dummy excursions. The restraint harness failed so that the dummy's energy was absorbed by the handrail which contacted the dummy's abdomen and the upper torso and legs flexed around the handrail. The right-hand bail hook disengaged from the seat back and the under structure support brace on the right-hand side of the seat collapsed.



Test No:

A-072

Test Date:

19 May 1969

Restraint Code No.:

C-5

Restraint Description:

Sears Seat No. 5516

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

No damage to either the dummy or to the restraint system was observed. The dummy experienced a high g loading on the head.



Test No:

A-073

Test Date:

5 June 1969

Restraint Code No.:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation: -

No damage was experienced by either the dummy or the restraint system. Seat belt and accelometer readings were quite low.



Test No:

A-074

Test Date:

6 June 1969

Restraint Code No.:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing

Dummy Attitude:

Sitting

Test Observation:

There was no damage experienced by either the dummy or the restraint system. The seat belt loads were similar in this test to previous tests on this restraint system. However, the accelometer readings experienced by the dummy were somewhat higher than previous tests.



Test No:

A-075

Test Date:

6 June 1969

Restraint Code No.:

C-17

Restraint Description: Strolee Seat No. 509

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

The headrest would not stay up behind the dummy's head in the initial test setup due to the lack of support structure. The hooks on the child seat vest-restraint pass over the shoulder and are directed downward to an attachment point on the seat back. It is possible that this could lead to compression of the back of the dummy. This seat, however, is on the small side for a 3-year dummy. There was no damage to the dummy in the test, but the excursion experienced was quite high. The buckle over the right shoulder attaching the vest to the dummy failed. Also the bail hooks on the child's seat were bent during the test.





Test No:

A-076

Test Date:

16 June 1969

Restraint Code No.:

C-13

Restraint Description: Peterson's Swinger Seat Model No. 60EC.

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

There was no damage observed to the dummy. The accelerometer readings for the head and chest revealed very low loadings. However, the excursion experienced by the dummy, because the adult seat back was badly deformed during the test due to the force supplied by the bail structures, was quite large even though the dummy did not contact the body buck on which the seat was mounted. The child's seat bails were bent badly. Also the child seat belt slipped in the adjustment buckle.





Test No:

A-078

Test Date:

23 June 1969

Restraint Code No.:

C-33

Restraint Description:

Voplex Harness C-2000

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing


Dummy Attitude:


Sitting

Test Observation:

There was no damage apparent to either the dummy or to the restraint system. The excursion experienced to the dummy was minimal. Belt and accelometer readings were low.







Test No:

A-079

Test Date:

24 June 1969

Restraint Code No.:

C-18

Restraint Description:

Strolee Seat No. 587

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level

18

Impact Direction:

Forward facing


Dummy Attitude:


Sitting

Test Observation:

The under structure of the child's seat collapsed during this test.

The one-eighth by five-eighth inch steel braces bent and the rivets broke where they were attached to the tubular feet. The wire restraint belt Y hook came out of the belt. The head of the dummy hit the dashboard on the body buck leading to extremely high g loadings.





Test No.:

A-080

Test Date:

24 June 1969

Restraint Code No.:

C-30

Restraint Description:

Mark IV Monitor Harness No. 61B12890

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level

18

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was experienced either by the dummy or by the restraint system. The loads experienced by the dummy were minimal and its excursion was quite low although the harness did appear to slip down into the abdnominal area.





Test No:

A-081

Test Date:

25 June 1969

Restraint Code No.:

C-35

Restraint Description:

American Safety Harness No. CV250

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Forward facing


Dummy Attitude:

Sitting

Test Observation:

No damage was experienced either by the dummy or by the restraint system. The accelometer readings for the head were quite high. The upper torso and the head of the dummy were observed to pitch forward and jackknife over the restraint system to the extent that the dummy's head touched the adult seat cushion.





Test No: A-082

Test Date: 25 June 1969

Restraint Code No.: C-35

Restraint Description: American Safety Harmess No. CV250

Dummy: 3 year

Sled Velocity: 30 mph


Sled G-level: 18

Impact Direction: Forward facing


Dummy Attitude: Sitting

Test Observation:

There appeared to be no damage either to the dummy or to the restraint system. The loadings experienced in both the dummy's head and chest were quite high in this test. Again the upper torso and head of the dummy pitched forward and contacted the adult seat cushion.



NOT REPRODUCIBLE



Test No:

A-089

Test Date:

3 July 1969

Restraint Code No.:

C-1

Restraint Description:

Ford Tot-Guard

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Side impact

Dummy Attitude:


Sitting

Test Observation:

No observable damage was experienced by the dummy. The head superior-inferior and the chest left and right accelometer readings were quite high. The sideways motion experienced by the head would have allowed contact with any adjacent door structures. The sidewall of the upper section of the restraint system was permanently deformed. This section of the restraint system also slid off the lower seat cushion.



NOT REPRODUCIBLE



Test No: A-090

Test Date: 8 July 1969

Restraint Code No.: C-4

Restraint Description: Sears Seat No. 28A6400C

Dummy: 3 year

Sled Velocity: 20 mph


Sled G-level: 18


Impact Direction: Side facing

Dummy Attitude: Sitting

Test Observation:

No damage was experienced by the dummy. The bottom of the pedestal seat dug into the seat cushion of the adult seat causing the dummy to pitch sideways. Any door structures which would have been present would have been contacted by the dummy head.





Test No:

A-091

Test Date:

8 July 1969

Restraint Code No.:

C-4

Restraint Description:

Sears Seat 28A6400C

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Side impact

Dummy Attitude:


Sitting


Test Observation:

There was no apparent damage to either the dummy or to the restraint system. The dummy received extreme side bending about the mid-torso. The head accelometer readings were very high. Any vehicle side structures adjacent to the child system would have been contacted.



NOT REPRODUCIBLE





Test No:

A-092

Test Date:

9 July 1969

Restraint Code No.:

C-5

Restraint Description:

Sears Seat No. 5516

Dummy:

3 year

Sled Velocity:

20 mph

Sled G-level:

18

Impact Direction:


Side impact


Dummy Attitude:

Sitting

Test Observation:

The restraint system and dummy received no damage. Accelerometers mounted in the head and chest indicated moderate g levels. The dummy jackknifed to the side and would have contacted any adjacent door structures. The head pitched downward to a level near the seat cushion.





Test No: A-093

Test Date: 10 July 1969

Restraint Code No.: C-5

Restraint Description: Sears Seat No. 5516

Dummy: 3 year

Sled Velocity: 30 mph


Sled G-level: 18

Impact Direction: Side impact


Dummy Attitude: Sitting


Test Observation:

The child seat tipped toward the door structures and the dummy pitched violently downward and would have contacted any adjacent structures. The dummy was wedged extremely tightly under the lap belt. The left thigh would probably have been abraded hadly in actual case. Both the head and chest superior-inferior accelerometers readings were quite high.



NOT REPRODUCIBLE





Test No:

A-094

Test Date:

10 July 1969

Restraint Code No.:

C-4

Restraint Description:

Sears Seat No. 28A6400C

Dummy:

3 year

Sled Velocity:

30 mph

Sled G-level:

18

Impact Direction:


Side impact

Dummy Attitude:


Sitting


Test Observation:

The dummy pitched violently toward the side of the seat structure. The right arm of the dummy flew off. The lap belt loadings were extremely high within 1150 and 2300 lbs being recorded on the two sides of the belt.



NOT REPRODUCIBLE





HSRI SUMMARY DATA SHEET (MH-11-6962

Test No: A-095

Test Date: 11 July 1969

Restraint Code No.: C-16

Restraint Description: Klippan Safety Seat

Dunny:


Sled Velocity: 20 mph

Sled G-level: 18
Impact Direction: Side impact

Dunminy Attitude: Sitting

Test Observation:

of the molded resin fiberglass shell. The spring on the upper rear retaining the left hand strap retaining the Klippan seat to the adult seat tore out strap was deformed somewhat. The seat needs better anchoring of the side Petuining straps. Unfortunately both the seat and the dummy were ejected The dummy received an extremely gentle ride in this test. in this test.



NOT REPRODUCIBLE

