

Technical Note on
Software for ME 487

Report No. UM-MEAM-91-01

Instructor: Prof. Kannatey-Asibu Jr.

Author: Chih-Kuo Fang

engn

VMR0524

Technical Note on **Software for ME 487**

Instructor: Prof. Kannatey-Asibu Jr.
Author: Chih-Kuo Fang

1. ABSTRACT

An interactive software package on a Macintosh for ME487 is developed, which involves the thermal analysis of weldments, calculation of residual stresses and distortion, and design of weldments. This technical note provides an overview of the software, and gives step-by-step instructions. Following these procedures, students can use this software easily even when not familiar with the Macintosh, and save a lot of time on the calculations of various aspects of welding problems.

2. INTRODUCTION

This software can solve three aspects of welding problems:

A. Thermal Analysis of Weldments:

Analysis of temperature distribution and cooling rate is an essential aspect of any welding problems, since these affect the final structure of the material as well as the stresses and distortion induced. Simplified closed form analyses have been undertaken.

B. Residual Stresses and Distortion:

The analyses under thermal aspects are extended to include residual stresses and distortion. Since this area is still in its infancy in research, the software developed only encompasses simplified closed form solutions.

C. Design of Weldments:

The design of weldments involves the determination of weld size (crosssectional area and length). This software provides a useful tool for students when designing welding systems for application.

Hence the software is divided into the following sections:

- (1) crosssectional area of fused zone
- (2) temperature distribution
- (3) peak temperature
- (4) determining thin or thick plate
- (5) cooling rate
- (6) solidification rate
- (7) bead width
- (8) residual stress
- (9) weld distortion
- (10) weldment design

3. STEP-BY-STEP INSTRUCTIONS

1. If you use a Macintosh SE computer, switch on the machine.
If you use a Macintosh II, IIx, IIcx, or IIci computer, press the upper rightmost key (marked by a triangle) on the keyboard.
2. Insert the diskette containing the software for ME487.
3. Double click the "ME487.apl" icon to open the file. You will see:

```
*****
ME487 WELDING SOFTWARE
*****
MAIN MENU
-----
1) CROSSSECTIONAL AREA OF FUSED ZONE
2) TEMPERATURE DISTRIBUTION
3) PEAK TEMPERATURE
4) DETERMINING THIN OR THICK PLATE
5) COOLING RATE
6) SOLIDIFICATION RATE
7) BEAD WIDTH
8) RESIDUAL STRESS
9) WELD DISTORTION
10) WELDMENT DESIGN
-----
0) EXIT
*****
ENTER NUMBER ?
```

4. Enter the corresponding number of the item of interest.
5. Follow the instructions on the screen to response. Be careful of the data type (real or integer) when you enter your input data. If the default value is real, you should enter real data also.

Example: If you see:

WELD DENSITY (kg/m³) ? (e.g. 8000.0)

where "8000.0" is the default value.

If the value which you are going to enter is the same as the default value, just press <return>, otherwise, you should enter your data, say "5000.0" instead of "5000" to avoid errors.

4. DEMONSTRATION

A_w = crosssectional area of fused zone
 C = specific heat
 d = root opening
 E = voltage
 h = plate thickness
 I = current

K = thermal conductivity
 K_0 = modified Bessel function of the 2nd kind and order zero
 L = latent heat of fusion
 l = weld length
 P = applied load
 Q = heat input
 q_1 = energy required to melt a unit volume of material
 R = distance from the fusion zone to the point of interest = $|y| - w/2$
 r = distance from the arc to the point of interest
 S = (total) shrinkage
 S_0 = first pass shrinkage
 T = temperature of the point of interest
 T_m = melting temperature
 T_0 = ambient temperature
 t_s = solidification time
 V = welding velocity
 W = accumulated weight of weld metal deposited per unit weld length
 W_0 = initial W (first pass)
 w = bead width
 α = $K/\rho C$
 ϵ_A = measured strain (from strain gauge A)
 ϵ_B = measured strain (from strain gauge B)
 ϵ_C = measured strain (from strain gauge C)
 ϵ_x = strain in x-direction
 ϵ_y = strain in y-direction
 $\epsilon_{1,2}$ = principal strain
 ρ = weldment density
 ρ_w = weld density
 ν = poisson's ratio
 τ_{max} = maximum shear stress
 η_1 = heat transfer efficiency
 η_2 = melting efficiency

(1) Crosssectional Area of Fused Zone

$$A_w = \frac{\eta_1 \eta_2 EI}{q_1 V}$$

where

$$q_1 = \rho_w [L + C (T_m - T_0)]$$

(2) Temperature Distribution

For thick plate (3-Dimensional)

$$T - T_0 = \frac{Q}{2\pi r K} e^{-V \left(\frac{r+x}{2\alpha} \right)}$$

For thin plate (2-Dimensional)

$$T - T_0 = \frac{Q}{2\pi r K} e^{-\frac{Vx}{2\alpha}} K_0 \left(\frac{Vx}{2\alpha} \right)$$

(3) Peak Temperature

$$\frac{1}{T - T_0} = \frac{4.13\rho h V C R}{Q} + \frac{1}{T_m - T_0}$$

(4) Determining Thin or Thick Plate

$$\tau = h \sqrt{\frac{\rho C V (T - T_0)}{Q}}$$

Thin plate when $\tau < 0.6$

Thick plate when $\tau > 0.9$

(5) Cooling Rate

For thick plate (3-Dimensional)

$$\frac{dT}{dt} = \frac{-2\pi K V}{Q} (T - T_0)^2$$

For thin plate (2-Dimensional)

$$\frac{dT}{dt} = -2\pi K \rho C \left(\frac{Vh}{Q} \right)^2 (T - T_0)^3$$

(6) Solidification Rate

$$t_s = \frac{LQ}{2\pi K \rho C V (T - T_m)^2}$$

(7) Bead Width

For thick plate (3-Dimensional)

$$Q = 1.25 \pi w K T_m \left(0.4 + \frac{Vw}{4\alpha} \right)$$

For thin plate (2-Dimensional)

$$Q = 8KhT_m \left(0.2 + \frac{V_w}{4\alpha} \right)$$

(8) Residual Stress

$$\epsilon_A = \epsilon_x \cos^2 \theta_A + \epsilon_y \sin^2 \theta_A + \gamma_{xy} \sin \theta_A \cos^2 \theta_A$$

$$\epsilon_B = \epsilon_x \cos^2 \theta_B + \epsilon_y \sin^2 \theta_B + \gamma_{xy} \sin \theta_B \cos^2 \theta_B$$

$$\epsilon_C = \epsilon_x \cos^2 \theta_C + \epsilon_y \sin^2 \theta_C + \gamma_{xy} \sin \theta_C \cos^2 \theta_C$$

$$\epsilon_{1,2} = \frac{\epsilon_x + \epsilon_y}{2} \pm \frac{1}{2} \sqrt{(\epsilon_x - \epsilon_y)^2 + \gamma_{xy}^2}$$

$$\sigma_1 = - \frac{E}{1 - \nu^2} (\epsilon_1 + \nu \epsilon_2)$$

$$\sigma_2 = - \frac{E}{1 - \nu^2} (\epsilon_2 + \nu \epsilon_1)$$

$$\tau_{\max} = |\sigma_1 - \sigma_2| / 2$$

(9) Weld Distortion

(1) Transverse Shrinkage

(a) Butt Welds

For Single Pass

$$S = \alpha \frac{A}{h} + \beta d$$

where $\alpha = 0.2$ for inch units (5.16 for mm units)

For Multipass Weld

$$S = S_0 + b \log \frac{W}{W_0}$$

$b = \text{constant}$

(b) Fillet Welds

$$S = \alpha \frac{\text{Leg of Fillet}}{\text{Plate thickness}} \quad (\text{inches})$$

$\alpha = 0.06$ for lap-joint, 0.04 for T-joint

(2) Longitudinal Shrinkage

$$S = \frac{0.12IL}{10^5 h} \quad (\text{inches})$$

(3) Angular Distortion

$$\delta = \phi l \left[0.25 - \left(\frac{x}{l} - 0.5 \right)^2 \right]$$

$$\text{where } \phi = \frac{\phi_0}{1 + \frac{2D}{lC}}, \quad D = \frac{Eh^3}{12(1-\nu^2)}, \quad C = \frac{h^4}{1+0.2W}$$

(10) Weldment Design

(1) Butt Welds

$$\sigma = \frac{P}{hl}, \quad \tau = \frac{P}{hl}$$

(2) Fillet Welds

For Tension Test

$$\tau = \frac{P}{0.707hl} \quad \text{where } h = \text{weld leg}$$

For Torsion Test

Direct shear $\tau_1 = P/A$ Where A = throat area

Shear due to torsion $\tau_2 = Tr/J$

where T = Torque = PL

J = area polar moment of inertia of weld group about centroid

For Bending Test

Direct shear $\tau_1 = P/A$

Bending Stress $\sigma = \frac{MC}{I}$

where M = PA, C = d/2 + h

I = 0.707 h I_u

I_u = unit area moment of inertia

APPENDIX

```

PROGRAM ME487
DOUBLE PRECISION BK,BI,BJ,RKK,SS,A,EX,THK
1  WRITE (9,10)
10  FORMAT ('*****'//
;      '          ME487  WELDING  SOFTWARE          '//
;      '*****'//
;      '          MAIN MENU          '//
;      '-----'//
;      ' 1)  CROSSECTIONAL AREA OF FUSED ZONE      '/
;      ' 2)  TEMPERATURE DISTRIBUTION            '/
;      ' 3)  PEAK TEMPERATURE                    '/
;      ' 4)  DETERMINING THIN OR THICK PLATE      '/
;      ' 5)  COOLING RATE                        '/
;      ' 6)  SOLIDIFICATION RATE                 '/
;      ' 7)  BEAD WIDTH                          '/
;      ' 8)  RESIDUAL STRESS                     '/
;      ' 9)  WELD DISTORTION                     '/
;      '10)  WELDMENT DESIGN                     '/
;      '-----'//
;      '          0)  EXIT                        '//
;      '*****'//
;      ' ENTER NUMBER ?                          '/')
      PI=3.1415926
11  FORMAT (/A50)
21  FORMAT (F9.4)
22  FORMAT (F12.5)
20  READ (9,30) I
30  FORMAT (I2)
      GO TO (100,200,300,400,500,600,700,800,900,1000) I
      GO TO 9999
C-----NO.1-----
100  WRITE (9,11) 'HEAT TRANSFER EFFICIENCY ? (e.g. 0.95)'
      READ (9,21) F1
      IF (F1.EQ.0.) F1=.95
      WRITE (9,11) 'MELTING EFFICIENCY ? (e.g. 0.97)'
      READ (9,21) F2
      IF (F2.EQ.0.) F2=.97
      WRITE (9,11) 'WELD DENSITY (kg/m^3) ? (e.g. 8000.0)'
      READ (9,22) THO

```

```

IF (THO.EQ.0.) THO=8000.
THO=THO/1000000000.
WRITE (9,11) 'SPECIFIC HEAT (kJ/kg.K) ? (e.g. 0.850) '
READ (9,22) C
IF (C.EQ.0.) C=.85
C=C*1000
WRITE (9,11) 'LATENT HEAT (kJ/kg) ? (e.g. 272.0) '
READ (9,21) HL
IF (HL.EQ.0.) HL=272.
HL=HL*1000.
WRITE (9,11) 'MELTING TEMPERATURE (C) ? (e.g. 1465.0) '
READ (9,21) TM
IF (TM.EQ.0.) TM=1465.
WRITE (9,11) 'AMBIENT TEMPERATURE (C) ? (e.g. 20.0) '
READ (9,21) TA
IF (TA.EQ.0.) TA=20.
WRITE (9,11) 'CURRENT (Amp) ? (e.g. 250.0) '
READ (9,21) EI
IF (EI.EQ.0.) EI=250.
WRITE (9,11) 'VOLTAGE (Volts) ? (e.g. 30.0) '
READ (9,21) E
IF (E.EQ.0.) E=30.
WRITE (9,11) 'WELDING SPEED (mm/s) ? (e.g. 12.0) '
READ (9, 22) V
IF (V.EQ.0.) V=12.
Q=THO*(HL+C*(TM-TA))
AW=(F1*F2*E*EI)/(Q*V)
WRITE (9,190) AW
190  FORMAT ('CROSSSECTIONAL AREA =' F10.3, ' (mm^2)')
      PAUSE
      GO TO 1

C-----NO. 2-----
200  WRITE (9,11) 'ENTER DIMENSION ? (2=THIN PLATE, 3=THICK PLATE) '
      READ (9,202) I
      IF (I.EQ.0) I=2
202  FORMAT (I1)
      WRITE (9,11) 'THERMAL CONDUCTIVITY (J/s.mm.C) ? ( e.g. 0.05) '
      READ (9,21) THK
      IF (THK.EQ.0.) THK=.05

```

```

WRITE (9,11) 'AMBIENT TEMPERATURE (C) ? (e.g. 25.0)'
READ (9,21) TA
IF (TA.EQ.0.) TA=25.
WRITE (9,11) 'WELD DENSITY (kg/m^3) ? (e.g. 8000.0)'
READ (9,22) THO
IF (THO.EQ.0.) THO=8000.
THO=THO/1000000000.
WRITE (9,11) 'SPECIFIC HEAT (kJ/kg.K) ? (e.g. 0.850)'
READ (9,21) C
IF (C.EQ.0.) C=.85
C=C*1000.
ALPHA=THK/(THO*C)
WRITE (9,11) 'WELDING SPEED (mm/s) ? (e.g. 10.0)'
READ (9, 21) V
IF (V.EQ.0.) V=10.
WRITE (9,205)
205  FORMAT ('ENTER HEAT-INPUT OR VOLTAGE-CURRENT ? ',
;      '1=HEAT-INPUT, 2=VOLATGE-CURRENT')
READ (9,30) K
IF (K.EQ.0) K=1
GO TO (206,207) K
206  WRITE (9,11) 'HEAT INPUT (J/s) ? (e.g. 6000.0)'
READ (9,22) Q
IF (Q.EQ.0.) Q=6000.
GO TO 209
207  WRITE (9,11) 'VOLTAGE (Volts) ? (e.g. 30.0)'
READ (9,21) E
IF (E.EQ.0.) E=30.
WRITE (9,11) 'CURRENT (Amp) ? (e.g. 200.)'
READ (9,21) EI
IF (EI.EQ.0.) EI=200.
WRITE (9,11) 'HEAT TRANSFER EFFICIENCY ? (e.g. 1.0)'
READ (9,21) F1
IF (F1.EQ.0.) F1=1.
Q=F1*E*EI
209  WRITE (9,210)
210  FORMAT ('COORDINATES W.R.T. HEAT SOURCE. X (mm)= ? (e.g. -8.0)'
;      '!!! X<0 IF BEHIND THE HEAT SOURCE')
READ (9,21) X
IF (X.EQ.0.) X=-8.0

```

```

WRITE (9,11) 'Y (mm) = ? (e.g. 5.0)'
READ (9,21) Y
IF (Y.EQ.0.) Y=5.0
IF (I.NE.3) GO TO 270
C-----3-D
WRITE (9,11) 'Z (mm)= ? (e.g. 3.0) '
READ (9,21) Z
IF (Z.EQ.0.) Z=5.0
R=(X**2+Y**2+Z**2)**.5
EX=-V*(R+X)/(2.*ALPHA)
T=Q/(2.*PI*R*THK)*EXP(EX) + TA
WRITE (9,265) T
265  FORMAT ('3-D TEMPERATURE = ' F8.3, ' (C)')
      PAUSE
      GO TO 1
270  IF (I.NE.2) GO TO 1
C-----2-D
WRITE (9,11) 'THICKNESS (mm) =? (e.g. 8.0) '
READ (9,22) H
IF (H.EQ.0.) H=8.0
R=(X**2+Y**2)**.5
EX=V*X/(2.*ALPHA)
A=V*R/(2.*ALPHA)
BI=0
BJ=0
DO 295 K=1,70
      RKK=1
      SS=0
          DO 285 I=1,K
              RKK=RKK*I
              S=I
              SS=SS+1./S
285          CONTINUE
          RK=K
          BI=BI+1./(RKK*RKK)*((A/2.)**(2.*RK))
          BJ=BJ+((A/2.)**(2.*RK))/(RKK*RKK)*SS
295  CONTINUE
BK=- (DLOG(A/2.)+0.5772157)*(BI+1.)+BJ
T=Q/(2.*PI*THK*H)*EXP(-EX)*BK+TA

```

```

WRITE (9,299) T
299  FORMAT ('2-D TEMPERATURE = ' F8.3, ' (C)')
      PAUSE
      GO TO 1
C-----NO.3-----
300  WRITE (9,11) 'MELTING TEMPERATURE (C) ? (e.g. 1500.0)'
      READ (9,21) TM
      IF (TM.EQ.0.) TM=1500.
      WRITE (9,11) 'AMBIENT TEMPERATURE (C) ? (e.g. 25.0)'
      READ (9,21) TA
      IF (TA.EQ.0.) TA=25.
      WRITE (9,11) 'WELD DENSITY (kg/m^3) ? (e.g. 8000.0)'
      READ (9,22) THO
      IF (THO.EQ.0.) THO=8000.
      THO=THO/1000000000.
      WRITE (9,11) 'SPECIFIC HEAT (kJ/kg.K) ? (e.g. 0.850)'
      READ (9,22) C
      IF (C.EQ.0.) C=.85
      C=C*1000.
      ALPHA=THK/(THO*C)
      WRITE (9,11) 'WELDING SPEED (mm/s) ? (e.g. 10.0)'
      READ (9, 21) V
      IF (V.EQ.0.) V=10.
      WRITE (9,305)
305  FORMAT ('ENTER HEAT-INPUT OR VOLTAGE-CURRENT ? ',
;          '1=HEAT-INPUT, 2=VOLATGE-CURRENT')
      READ (9,30) K
      IF (K.EQ.0) K=1
      GO TO (306,307) K
306  WRITE (9,11) 'HEAT INPUT (J/s) ? (e.g. 6000.0)'
      READ (9,22) Q
      IF (Q.EQ.0.) Q=6000.
      GO TO 309
307  WRITE (9,11) 'VOLTAGE (Volt) ? (e.g. 30.0)'
      READ (9,21) E
      IF (E.EQ.0.) E=30.
      WRITE (9,11) 'CURRENT (Amp) ? (e.g. 200.)'
      READ (9,21) EI
      IF (EI.EQ.0.) EI=200.
      WRITE (9,11) 'HEAT TRANSFER EFFICIENCY ? (e.g. 1.0)'

```

```

READ (9,21) F1
IF (F1.EQ.0.) F1=1.
Q=F1*E*EI
309 WRITE (9,11) 'THICKNESS (mm) =? (e.g.8.0) '
READ (9,21) H
IF (H.EQ.0.) H=8.
WRITE (9,11) 'DISTANCE FROM FUSION ZONE (mm) ? (e.g. 3.42) '
READ (9,21) R
IF (R.EQ.0.) R=3.42
TI= 4.13*THO*H*V*C*R/Q + 1/(TM-TA)
TP= TA + 1./TI
WRITE (9,390) TP
390 FORMAT ('PEAK TEMPERATURE = ' F10.3, ' (C)')
PAUSE
GO TO 1
C-----NO.4-----
400 WRITE (9,11) ' TEMPERATURE (C) ? (e.g. 600.0) '
READ (9,21) T
IF (T.EQ.0.) T=600.
WRITE (9,11) 'AMBIENT TEMPERATURE (C) ? (e.g. 25.0) '
READ (9,21) TA
IF (TA.EQ.0.) TA=25.
WRITE (9,11) 'WELD DENSITY (kg/m^3) ? (e.g. 7000.0) '
READ (9,22) THO
IF (THO.EQ.0.) THO=7000.
THO=THO/1000000000.
WRITE (9,11) 'SPECIFIC HEAT (kJ/kg.K) ? (e.g. 0.50) '
READ (9,21) C
IF (C.EQ.0.) C=.5
C=C*1000.
ALPHA=THK/(THO*C)
WRITE (9,11) 'WELDING SPEED (mm/s) ? (e.g. 6.0) '
READ (9, 21) V
IF (V.EQ.0.) V=6.
WRITE (9,405)
405 FORMAT ('ENTER HEAT-INPUT OR VOLTAGE-CURRENT ? ',
;          '1=HEAT-INPUT, 2=VOLATGE-CURRENT')
READ (9,30) K
IF (K.EQ.0) K=2

```

```

GO TO (406,407) K
406 WRITE (9,11) 'HEAT INPUT (J/s) ? (e.g. 6750.0)'
READ (9,22) Q
IF (Q.EQ.0.) Q=6750.
GO TO 409
407 WRITE (9,11) 'VOLTAGE (Volt) ? (e.g. 30.0)'
READ (9,21) E
IF (E.EQ.0.) E=30.
WRITE (9,11) 'CURRENT (Amp) ? (e.g. 250.)'
READ (9,21) EI
IF (EI.EQ.0.) EI=250.
WRITE (9,11) 'HEAT TRANSFER EFFICIENCY ? (e.g. 0.9)'
READ (9,21) F1
IF (F1.EQ.0.) F1=.9
Q=F1*E*EI
409 WRITE (9,11) 'THICKNESS (mm) = ? (e.g.3.0) '
READ (9,21) H
IF (H.EQ.0.) H=3.
TAU=H*(THO*C*V*(T-TA)/Q)**0.5
WRITE (9,460) TAU
460 FORMAT (' TAU = ' F6.3)
IF (TAU.LT.0.6) THEN
WRITE (9,11) 'THIN PLATE'
ELSE IF (TAU.GT.0.9) THEN
WRITE (9,11) 'THICK PLATE'
ELSE
WRITE (9,11) 'UNDETERMINED'
ENDIF
PAUSE
GO TO 1
C-----NO.5-----
500 WRITE (9,11) ' TEMPERATURE (C) ? (e.g. 400.0)'
READ (9,21) T
IF (T.EQ.0.) T=400.
WRITE (9,11) 'AMBIENT TEMPERATURE (C) ? (e.g. 30.0)'
READ (9,22) TA
IF (TA.EQ.0.) TA=30.
WRITE (9,505)
505 FORMAT ('ENTER HEAT-INPUT OR VOLTAGE-CURRENT ? ',
; '1=HEAT-INPUT, 2=VOLATGE-CURRENT')

```



```

READ (9,30) K
IF (K.EQ.0) K=2
GO TO (506,507) K
506 WRITE (9,11) 'HEAT INPUT (J/s) ? (e.g. 6375.0) '
READ (9,22) Q
IF (Q.EQ.0.) Q=6375.
GO TO 509
507 WRITE (9,11) 'VOLTAGE (Volt) ? (e.g. 30.0) '
READ (9,21) E
IF (E.EQ.0.) E=30.
WRITE (9,11) 'CURRENT (Amp) ? (e.g. 250.) '
READ (9,21) EI
IF (EI.EQ.0.) EI=250.
WRITE (9,11) 'HEAT TRANSFER EFFICIENCY ? (e.g. 0.85) '
READ (9,21) F1
IF (F1.EQ.0.) F1=.85
Q=F1*E*EI
509 WRITE (9,11) 'THERMAL CONDUCTIVITY (J/s.mm.C) ? ( e.g. 0.0456) '
READ (9,22) THK
IF (THK.EQ.0.) THK=.0456
WRITE (9,11) 'WELDING SPEED (mm/s) ? (e.g. 8.0) '
READ (9, 21) V
IF (V.EQ.0.) V=8.
WRITE (9,11) 'ENTER DIMENSION ? (2=THIN PLATE, 3=THICK PLATE) '
READ (9,30) I
IF (I.EQ.0) I=2
IF (I.NE.3) GO TO 550
C-----3-D
DT=-2*PI*THK*V/Q*(T-TA)**2
WRITE (9,520) DT
520 FORMAT ('COOLING RATE = ' F10.3, ' (C/s)')
PAUSE
GO TO 1
550 IF (I.NE.2) GO TO 1
C-----2-D
WRITE (9,11) 'WELD DENSITY (kg/m^3) ? (e.g. 7870.0) '
READ (9,22) THO
IF (THO.EQ.0.) THO=7870.
THO=THO/1000000000.

```

```

WRITE (9,11) 'SPECIFIC HEAT (kJ/kg.K) ? (e.g. 0.595)'
READ (9,21) C
IF (C.EQ.0.) C=.595
C=C*1000.
WRITE (9,11) 'THICKNESS (mm) = ? (e.g.9.0) '
READ (9,22) H
IF (H.EQ.0.) H=9.
DT=-2.*PI*THK*THO*C*(V*H/Q)**2*(T-TA)**3
WRITE (9,599) DT
599  FORMAT ('COOLING RATE = ' F10.3, ' (C/s) ' )
      PAUSE
      GO TO 1
C-----NO.6-----
600  WRITE (9,11) 'SPECIFIC HEAT (kj/kg.K) ? (e.g. 0.5)'
      READ (9,21) C
      IF (C.EQ.0.) C=.5
      C=C*1000.
      WRITE (9,11) 'LATENT HEAT (j/kg) ? (e.g. 2.5)'
      READ (9,21) HL
      IF (HL.EQ.0.) HL=2.5
      WRITE (9,11) 'MELTING TEMPERATURE (C) ? (e.g. 1600.0)'
      READ (9,21) TM
      IF (TM.EQ.0.) TM=1600.
      WRITE (9,11) 'AMBIENT TEMPERATURE (C) ? (e.g. 25.0)'
      READ (9,21) TA
      IF (TA.EQ.0.) TA=25.
      WRITE (9,605)
605  FORMAT ('ENTER HEAT-INPUT OR VOLTAGE-CURRENT ? ',
;      '1=HEAT-INPUT, 2=VOLATGE-CURRENT')
      READ (9,30) K
      IF (K.EQ.0) K=2
      GO TO (606,607) K
606  WRITE (9,11) 'HEAT INPUT (J/s) ? (e.g. 6750.0)'
      READ (9,22) Q
      IF (Q.EQ.0.) Q=6750.
      GO TO 609
607  WRITE (9,11) 'VOLTAGE (Volt) ? (e.g. 30.0)'
      READ (9,21) E
      IF (E.EQ.0.) E=30.

```

```

WRITE (9,11) 'CURRENT (Amp) ? (e.g. 250.)'
READ (9,21) EI
IF (EI.EQ.0.) EI=250.
WRITE (9,11) 'HEAT TRANSFER EFFICIENCY ? (e.g. 0.9)'
READ (9,21) F1
IF (F1.EQ.0.) F1=.9
WRITE (9,11) 'MELTING EFFICIENCY ? (e.g. 1.0)'
READ (9,21) F2
IF (F2.EQ.0.) F2=1.
Q=F1*F2*E*EI
609 WRITE (9,11) 'WELDING SPEED (mm/s) ? (e.g. 6.0)'
READ (9, 21) V
IF (V.EQ.0.) V=6.
WRITE (9,11) 'THERMAL CONDUCTIVITY (J/s.mm.C) ? ( e.g. 0.025)'
READ (9,21) THK
IF (THK.EQ.0.) THK=.025
WRITE (9,11) 'WELD DENSITY (kg/m^3) ? (e.g. 7000.0)'
READ (9,22) THO
IF (THO.EQ.0.) THO=7000.
THO=THO/1000000000.
T=2.*PI*THK*THO*C*V*(TM-TA)**2
TIME=HL*Q/T
WRITE (9,690) TIME
690 FORMAT ('SOLIDIFICATION TIME = ', F7.3, ' (sec)')
PAUSE
GO TO 1

C-----NO.7-----
700 WRITE (9,11) 'ENTER DIMENSION ? (2=THIN PLATE, 3=THICK PLATE)'
READ (9,702) I
702 FORMAT (I1)
IF (I.EQ.0) I=2
WRITE (9,11) 'MELTING TEMPERATURE (C) ? (e.g. 1500.0)'
READ (9,21) TM
IF (TM.EQ.0.) TM=1500.
WRITE (9,11) 'THERMAL CONDUCTIVITY (J/s.mm.C) ? ( e.g. 0.05)'
READ (9,21) THK
IF (THK.EQ.0.) THK=.05
WRITE (9,11) 'WELD DENSITY (kg/m^3) ? (e.g. 8000.0)'
READ (9,22) THO
IF (THO.EQ.0.) THO=8000.

```

```

THO=THO/1000000000.
WRITE (9,11) 'SPECIFIC HEAT (kj/kg.K) ? (e.g. 0.850) '
READ (9,21) C
IF (C.EQ.0.) C=.85
C=C*1000.
ALPHA=THK/(THO*C)
WRITE (9,11) 'WELDING SPEED (mm/s) ? (e.g. 10.0) '
READ (9, 21) V
IF (V.EQ.0.) V=10.
WRITE (9,11) 'HEAT INPUT (j/s) ? (e.g. 6000.0) '
READ (9,22) Q
IF (Q.EQ.0.) Q=6000.
IF (I.NE.3) GO TO 760
C-----3-D
CB=1.6*ALPHA/V
CC=4.*ALPHA*Q/(1.25*PI*THK*TM*V)
W=.5*(-CB+(CB**2.+4.*CC)**.5)
WRITE (9,750) W
750 FORMAT ('BEAD WIDTH = ' F10.3, ' (mm)')
PAUSE
GO TO 1
760 IF (I.NE.2) GO TO 1
C-----2-D
WRITE (9,11) 'THICKNESS (mm) = ? (e.g. 10.0) '
READ (9,21) H
IF (H.EQ.0.) H=10.
W=(4.*ALPHA/V)*(Q/(8.*THK*H*TM)-.2)
WRITE (9,790) W
790 FORMAT ('BEAD WIDTH = ' F10.3, ' (mm)')
PAUSE
GO TO 1
C-----NO.8-----
800 WRITE (9,805)
805 FORMAT ('*****'//
; ' ARRANGEMENT OF STRAIN GAUGES ' /
; '-----' /
; ' 1) DELTA OR STAR ROSETTE ' /
; ' 2) RECTANGULAR ROSETTE ' /
; '-----' /

```

```

;          '          0) MAIN MENU          '/
;          '*****'//
;          ' ENTER NUMBER ?          '/'

READ (9,30) II
IF (II.EQ.0) GO TO 1
WRITE (9,11) 'ELASTIC MODULUS (GPa) ? (e.g. 200.) '
READ (9,22) E
IF (E.EQ.0.) E=200.
WRITE (9,11) 'POISSON RATIO ? (e.g. 0.3) '
READ (9,21) V
IF (V.EQ.0.) V=.3
IF (II.NE.1) GO TO 830

```

C-----DELTA ROSETTE

```

WRITE(9,11) 'MEASURED STRAIN (0-DEGREE-GAGE) ? (e.g. 0.000750) '
READ (9,810) EA
810  FORMAT (F8.6)
IF (EA.EQ.0.) EA=.000750
WRITE(9,11) 'MEASURED STRAIN (120-DEGREE-GAGE) ? (e.g.0.000283) '
READ (9,810) EB
IF (EB.EQ.0.) EB=.000283
WRITE(9,11) 'MEASURED STRAIN (240-DEGREE-GAGE) ? (e.g.0.000500) '
READ (9,810) EC
IF (EC.EQ.0.) EC=.000500
EX=EA
EY=(2.*(EB+EC)-EA)/3.
EXY=2.*(EC-EB)/1.732
GO TO 840

```

C-----RECTANGULAR ROSETTE

```

830  WRITE(9,11) 'MEASURED STRAIN (0-DEGREE-GAGE) ? (e.g. 0.000750) '
READ (9,810) EA
IF (EA.EQ.0.) EA=.000750
WRITE(9,11) 'MEASURED STRAIN (45-DEGREE-GAGE) ? (e.g.0.000283) '
READ (9,810) EB
IF (EB.EQ.0.) EB=.000283
WRITE(9,11) 'MEASURED STRAIN (90-DEGREE-GAGE) ? (e.g.0.000500) '
READ (9,810) EC
IF (EC.EQ.0.) EC=.000500
EX=EA
EY=EC
EXY=2.*EB-EA-EC

```

```

C-----CALCULATE PRINCIPAL STRAIN
840  E1=(EX+EY)/2. + SQRT(((EX-EY)/2.)**2+EXY**2)
      E2=(EX+EY)/2. - SQRT(((EX-EY)/2.)**2+EXY**2)
C-----CALCULATE PRINCIPAL STRESS
      S1=-E/(1.-V**2)*(E1+V*E2)*1000.
      S2=-E/(1.-V**2)*(E2+V*E2)*1000.
      TAU=(S1-S2)/2.
      WRITE (9,890) S1,S2,TAU
890  FORMAT ('PRINCIPAL RESIDUAL STRESS 1:',F8.2,' (MPa)',
;          /'PRINCIPAL RESIDUAL STRESS 2:',F8.2,' (MPa)',
;          /'MAXIMAL SHEAR STRESS:',F8.2,' (MPa)' )
      PAUSE
      GO TO 800

C-----N0.9-----
900  WRITE (9,905)
905  FORMAT ('*****'//
;          '          WELD DISTORTION MENU          '/
;          '-----'//
;          ' 1) TRANSVERSE SHRINKAGE          '/
;          ' 2) LONGITUDINAL SHRINKAGE        '/
;          ' 3) ANGULAR DISTORTION           '/
;          '-----'//
;          '          0) MAIN MENU              '/
;          '*****'//
;          ' ENTER NUMBER ?                    '/)
      READ (9,30) II
      IF (II.EQ.0) GO TO 1
      GO TO (910,950,970) II

C----- 1) TRANSVERSE SHRINKAGE
910  WRITE (9,915)
915  FORMAT ('*****'//
;          '          TRANSVERSE SHRINKAGE MENU          '/
;          '-----'//
;          ' 1) BUTT WELDS                      '/
;          ' 2) FILLET WELDS                    '/
;          '-----'//
;          '          0) WELD DISTORTION MENU          '/
;          '*****'//
;          ' ENTER NUMBER ?                    '/)

```

```

      READ (9,30) III
      IF (III.EQ.0) GO TO 900
      GO TO (920,940) III
C----- 1) BUTT WELDS
920  WRITE (9,11) 'SINGLE OR MULTIPASS ? 1=SINGLE, 2=MULTIPASS'
      READ (9,30) J
      IF (J.NE.1) GO TO 930
C----- SINGLE PASS
      WRITE (9,11) 'WELD CROSSSECTIONAL AREA (in^2) ? (e.g. 0.207)'
      READ (9,21) A
      IF (A.EQ.0.) A=.207
      WRITE (9,11) 'THICKNESS (in) ? (e.g. 0.5)'
      READ (9,21) H
      IF (H.EQ.0.) H=.5
      WRITE (9,11) 'ROOT OPENING (in) ? (e.g. 0.125)'
      READ (9,21) D
      IF (D.EQ.0.) D=.125
      S=.2*A/H + .05*D
      WRITE (9,925) S
925  FORMAT ('SHRINKAGE =',F8.4,' (in) ')
      PAUSE
      GO TO 910
C-----MULTIPASS
930  WRITE (9,11) 'FIRST PASS SHRINKAGE (in) ? (e.g. 0.111)'
      READ (9,21) S0
      IF (S0.EQ.0.) S0=.111
      WRITE (9,11) 'WELD WEIGNT IN 1st-PASS (lb/in) ? (e.g.0.035)'
      READ (9,21) W0
      IF (W0.EQ.0.) W0=.035
      WRITE (9,11) 'ACCUMULATED WELD WEIGNT (lb/in) ? (e.g.0.065)'
      READ (9,21) W
      IF (W.EQ.0.) W=.065
      S=S0 + .37*ALOG(W/W0)
      WRITE (9,935) S
935  FORMAT ('TOTAL SHRINKAGE =',F8.4,' (in) ')
      PAUSE
      GO TO 910
C----- 2) FILLET WELDS
940  WRITE (9,11) 'LAP OR T-JOINT ? (1=LAP, 2=T-JOINT) '
      READ (9,30) ILT

```

```

IF (ILT.EQ.0) ILT=1
ALPHA=.06
IF (ILT.EQ.2) ALPHA=.04
WRITE (9,11) 'PLATE THICKNESS (in) ? (e.g. 0.75) '
READ (9,21) H
IF (H.EQ.0.) H=.75
WRITE (9,11) 'LEG OF FILLET (in) ? (e.g. 0.5) '
READ (9,21) FL
IF (FL.EQ.0.) FL=.5
S=FL/H*ALPHA
WRITE (9,945) S
945  FORMAT (/'SHRINKAGE = ',F6.3,' (in) ')
      PAUSE
      GO TO 910
C----- 2) LONGITUDINAL SHRINKAGE
950  WRITE (9,11) 'CURRENT (amp) ? (e.g. 300.) '
      READ (9,21) CI
      IF (CI.EQ.0.) CI=300.
      WRITE (9,11) 'PLATE THICKNESS (in) ? (e.g. 0.75) '
      READ (9,21) H
      IF (H.EQ.0.) H=.75
      WRITE (9,11) 'WELD LENGTH (in) ? (e.g. 20.0) '
      READ (9,21) WL
      IF (WL.EQ.0.) WL=20.
      S=.12*CI*WL/(100000.*H)
      WRITE (9,955) S
955  FORMAT (/'SHRINKAGE = ',F6.3,' (in) ')
      PAUSE
      GO TO 900
C----- 3) ANGULAR DISTORTION
970  WRITE (9,11) 'ELASTIC MODULUS (GPa) ? (e.g. 206.) '
      READ (9,22) E
      IF (E.EQ.0.) E=200.
      E=E/9.81*1000.
      WRITE (9,11) 'POISSON RATIO ? (e.g. 0.3) '
      READ (9,21) V
      IF (V.EQ.0.) V=.3
      WRITE (9,11) 'LENGH OF SPAN (mm) ? (e.g. 750.) '
      READ (9,21) SL

```



```

IF (SL.EQ.0.) SL=750.
WRITE (9,11) 'DISTANCE FROM JOINT (mm) ? (e.g. 375.)'
READ (9,21) X
IF (X.EQ.0.) X=375.
WRITE (9,11) 'PLATE THICKNESS (mm) ? (e.g. 19.)'
READ (9,21) H
IF (H.EQ.0.) H=19.
WRITE (9,11) 'WELD WEIGHT (g/cm) ? (e.g. 3.925)'
READ (9,21) W
IF (W.EQ.0.) W=3.925
WRITE (9,11) 'ANGULAR CHANGE IN A FREE JOINT (rad) ? (e.g.0.016)'
READ (9,21) PHI0
IF (PHI.EQ.0.) PHI0=.016
C=H**4/(1.+0.2*W)
D=E*H**3/(12.*(1-V**2))
PHI=PHI0/(1.+2*D/(SL*C))
DELTA=PHI*SL*(.25-(X/SL-.5)**2)
WRITE (9,975) DELTA
975  FORMAT ('DISTORTION = ',F6.3,' (mm) ')
      PAUSE
      GO TO 900

```

C-----NO.10-----

```

1000 WRITE (9,1015)
1015  FORMAT ('*****'//
;      '          WELDMENT DESIGN MENU          '/
;      '-----'//
;      ' 1) BUTT WELDS                          '/
;      ' 2) FILLET WELDS                        '/
;      '-----'//
;      '          0) MAIN MENU                    '/
;      '*****'//
;      ' ENTER NUMBER ?                          '/')
      READ (9,30) II
      IF (II.EQ.0) GO TO 1
      GO TO (1020,1040) II

```

C----- 1) BUTT WELDS

```

1020 WRITE (9,11) 'APPLIED LOAD (lb) ? (e.g. 40000.)'
      READ (9,1025) P
1025  FORMAT (F9.2)
      IF (P.EQ.0.) P=40000.

```

```

WRITE (9,11) 'PLATE THICKNESS (in) ? (e.g. 0.4)'
READ (9,21) H
IF (H.EQ.0.) H=.4
WRITE (9,11) 'WELD LENGTH (in) ? (e.g. 20.0)'
READ (9,21) WL
IF (WL.EQ.0.) WL=20.
STRESS=P/(H*WL)
WRITE (9,1030) STRESS
1030 FORMAT ('STRESS IN WELD = ',F10.2,' (psi) ')
PAUSE
GO TO 1000

C----- 2) FILLET WELD

1040 WRITE (9,1045)
1045 FORMAT ('*****'//
;          '          FILLET WELDS DESIGN MENU          '/
;          '-----'//
;          ' 1) TENSION TEST                               '/
;          ' 2) TORSION TEST                               '/
;          ' 3) BENDING TEST                               '/
;          '-----'//
;          '          0) WELD DESIGN MENU                  '/
;          '*****'//
;          ' ENTER NUMBER ?                               '/)
READ (9,30) II
IF (II.EQ.0) GO TO 1000
GO TO (1050,1070,1090) II

C----- 1) TENSION TEST

1050 WRITE (9,11) 'APPLIED LOAD (lb) ? (e.g. 40000.)'
READ (9,1055) P
1055 FORMAT (F9.2)
IF (P.EQ.0.) P=40000.
WRITE (9,11) 'PLATE THICKNESS (in) ? (e.g. 0.4)'
READ (9,21) H
IF (H.EQ.0.) H=.4
WRITE (9,11) 'WELD LENGTH (in) ? (e.g. 20.0)'
READ (9,21) WL
IF (WL.EQ.0.) WL=20.
STRESS=P/(.707*H*WL)
WRITE (9,1060) STRESS

```

```

1060 FORMAT ('SHEAR STRESS IN WELD = ',F10.2,' (psi) ')
      PAUSE
      GO TO 1040

C-----2) TORSION TEST
1070 WRITE (9,11) 'TORQUE (lb-in) ? (e.g. 35900.)'
      READ (9,1075) T
1075 FORMAT (F9.2)
      IF (T.EQ.0.) T=35900.
      WRITE (9,1080)
1080 FORMAT ('UNIT POLAR MOMENT OF INERTIA OF WELD GROUP',
;          'ABOUT CENTROID (in^3) ? (e.g. 20.833)' )
      READ (9,21) PJU
      IF (PJU.EQ.0.) PJU=20.833
      WRITE (9,11) 'WELD LEG (in) ? (e.g. 0.25)'
      READ (9,21) H
      IF (H.EQ.0.) H=.25
      WRITE (9,11) 'DISTANCE FROM CENTROID (in) ? (e.g. 2.15)'
      READ (9,21) R
      IF (R.EQ.0.) R=2.15
      PJ=.707*H*PJU
      TAU=T*R/PJ
      WRITE (9,1085) TAU
1085 FORMAT ('SHEAR STRESS DUE TO TORSION =',F8.2,' (psi)')
      PAUSE
      GO TO 1040

C----- 3) BENDING TEST
1090 WRITE (9,11) 'BEAM LENGTH (in) ? (e.g. 15.0)'
      READ (9,21) A
      IF (A.EQ.0.) A=15.
      WRITE (9,11) 'BEAM THICKNESS (in) ? (e.g. 1.)'
      READ (9,21) D
      IF (D.EQ.0.) D=1.
      WRITE (9,11) 'BEAM WIDTH (in) ? (e.g. 10.)'
      READ (9,21) B
      IF (B.EQ.0.) B=10.
      WRITE (9,11) 'WELD LEG (in) ? (e.g. 0.4)'
      READ (9,21) H
      IF (H.EQ.0.) H=.4
      WRITE (9,11) 'APPLIED LOAD (lb) ? (e.g. 2000.)'

```

```

      READ (9,1095) P
1095  FORMAT (F9.2)
      IF (P.EQ.0.) P=2000.
      SX=P*A*(D/2.+H)/(.707*H*B*D**2/2.)
      SY=0.
      SXY=P/(.707*H*B*2)
      S1=(SX+SY)/2. + SQRT(((SX-SY)/2.)**2+SXY**2)
      S2=(SX+SY)/2. - SQRT(((SX-SY)/2.)**2+SXY**2)
      WRITE (9,1100) S1,S2
1100  FORMAT ('PRINCIPAL STRESSES =',F11.2,' AND ',F11.2 , '(psi)')
      GO TO 1040
C-----END-----
9999  END

```

UNIVERSITY OF MICHIGAN



3 9015 02229 2547