

*Archives*

**UM-HSRI-81-32**

**A STUDY OF  
WINDSHIELD-RELATED INJURIES  
IN CARS OF  
JAPANESE MANUFACTURE**

**Appendices**

**Charles P. Compton  
James O'Day**

**FINAL REPORT  
JUNE 1981**



**THE UNIVERSITY OF MICHIGAN  
HIGHWAY SAFETY RESEARCH INSTITUTE**

APPENDIX B  
CPIR

The CPIR case reviews for front seat occupants of Japanese manufactured vehicles are included in this appendix. Although the statistics in Section 5 of this report were limited to the 55 occupants who were involved in frontal collisions, the cases in this appendix also include front seat occupants of Japanese cars involved in other-than-frontal collisions who had injuries attributed to windshield contact. In addition to the computerized case report, copies of the investigators' summaries are included for those cases in which the injury severity was AIS-3 or greater.

As in the NCCSS cases, these CPIR summaries have been arbitrarily numbered (from 1 through 84 as shown at the top of each page). The accident description section should be self-explanatory. Teams are identified by letter codes, which can be decoded by reference to the CPIR codebook. Referring to Case #1, for example, the file reference for this is AA 132 (or the 132nd case investigated by the Ann Arbor Multi-Disciplinary Accident Investigation Team). Variable numbers (shown as V-nn) refer to the variable list of the CPIR codebook, and that will show the range of possible codes. In Case #1, the accident configuration (Variable #59) is listed as "T", for a T-Intersection collision.

Referring to the vehicle section, impact speed is given in miles per hour, and was estimated by the investigator rather than computed from some particular formula. The VIN generally has 9's as the last 6 characters to protect privacy.

The "Areas Contacted" entry requires further explanation. This is coded as a "multiple response variable," and includes--in one eight-digit number--information on up to four separate areas contacted. In the CPIR protocol, investigators were asked to list the likely source of injury to a body region in order of probability of causing the indicated injury. For example, an occupant could contact both a windshield and the windshield header, with the most severe head injury resulting from the header contact. In this case the investigator should report header as the first probable injury cause, windshield as the second, etc. This procedure was not always followed consistently, however, and should not be depended upon.

The contact codes are shown in the excerpt from the CPIR codebook preceding the case listings. Consider the eight digit number as a set of four two-digit numbers. Each two-digit number indicates a possible contact for that body region. The number 99 is used to indicate either unknown or none. For example, in case #1 under "Overall Injury Description" the brain has no contacts indicated (all 9's), but the face in a contact with 12 (windshield), then 14 (A-pillar), and then 36 (unknown area but object exterior to case vehicle). The fourth possible contact is coded 99 (unknown or none).

As in the NCSS appendix, there are several list of subsets of the cases to make it easier to find specific topics. First there is a summary list of all (84) cases, similar to that shown for NCSS. Next there is a list of the five occupants who were restrained and struck the windshield. The third list is a tabulation of those cases not

involving a primary frontal crash, but having windshield contact injuries. The complement of this list constitutes those cases with primary frontal crash damage and windshield injuries.

The fourth list constitutes those cases with an Overall AIS of 3 or greater, and is the same as those cases for which the detailed team summaries are included.

SUMMARY LIST OF CPIR APPENDIX CASES

CASE#	TEAM CASE #	MAKE	MODEL	CDC-1	CDC-2	POSITION	BELTS	INJURY (AIS)		
1	AA 132	COLT	SUB/MINI	IMPORT	02RDAW3	00LDAQ1	FRONT	NONE	SERIOUS4	
2	AA 196	TOYOTA	COMPACT	01FZEW1	9900000	FRONT	NONE	MINOR 1		
3	4ME49	DATSUN	PICKUP	TRUCK	00TDH04	12FDEW2	FRONT LAP	80	MODERAT2	
4	BU 73 05	TOYOTA	SUB/MINI	IMPORT	12FYEW2	9900000	FRONT	NONE	CRITICL5	
5	BU 74 04	COLT	SUB/MINI	IMPORT	12FREN2	9900000	FRONT	NONE	MINOR 1	
6	CAL 72 286A	COLT	SUB/MINI	IMPORT	12FDEW1	9900000	FRONT	NONE	MINOR 1	
7	DTS 065 72	DATSUN	SUB/MINI	IMPORT	12FDAW7	00RDA01	FRONT	BOTH	88	FATAL 6
8	DTS 103 74	TOYOTA	COMPACT	02RYEW5	03RBEW1	FRONT	NONE	CRITICL5		
9	MGU 076 74	DATSUN	SUB/MINI	IMPORT	12FDEW2	9900000	FRONT	NONE	MINOR 1	
10	MGU 076 74	DATSUN	SUB/MINI	IMPORT	12FDEW2	9900000	FRONT	NONE	MINOR 1	
11	MGU 091 75	DATSUN	SUB/MINI	IMPORT	12FLEW2	12LZMS1	FRONT	NONE	MODERAT2	
12	MGU 094 75	DATSUN	SUB/MINI	IMPORT	11FDAW9	9900000	FRONT	NONE	FATAL 6	
13	MGU 094 75	DATSUN	SUB/MINI	IMPORT	11FDAW9	9900000	FRONT	NONE	CRITICL5	
14	C MI 006	SUBARU	SUB/MINI	IMPORT	01FREW2	03RBEW2	FRONT	NONE	SEVERE 3	
15	EPM 024 72	DATSUN	SUB/MINI	IMPORT	02RPEW4	01FDEW1	FRONT	NONE	MODERAT2	
16	EPM 034 72	TOYOTA	SUB/MINI	IMPORT	12FZEW2	9900000	FRONT	NONE	MINOR 1	
17	EPM 037 73	DATSUN	SUB/MINI	IMPORT	10LDEW2	9900000	FRONT	NONE	MINOR 1	
18	UNB 035 73	DATSUN	SUB/MINI	IMPORT	12FLEW1	9900000	FRONT	NONE	MINOR 1	
19	UNB 091 77	TOYOTA	SUB/MINI	IMPORT	12FZEW3	99F0000	FRONT	NONE	MODERAT2	
20	UNB 091 77	TOYOTA	SUB/MINI	IMPORT	12FZEW3	99F0000	FRONT	NONE	MINOR 1	
21	UNB 094 77	HONDA	SUB/MINI	IMPORT	00TPG03	12FDLW4	FRONT	NONE	MINOR 1	
22	UNM 17	TOYOTA	COMPACT	11FYEW5	9900000	FRONT	LAP	30	SEVERE 3	
23	UNM 33	DATSUN	UNK	TYPE CAR	04RPMW2	9900000	FRONT	NONE	MODERAT2	
24	UNM 61	DATSUN	SUB/MINI	IMPORT	02RZEW3	9900000	FRONT	NONE	MINOR 1	
25	UNM 61	DATSUN	SUB/MINI	IMPORT	02RZEW3	9900000	FRONT	NONE	MINOR 1	
26	UNM 81	DATSUN	SUB/MINI	IMPORT	01FDEW2	9900000	FRONT	NONE	MODERAT2	
27	UNM 94	DATSUN	SUB/MINI	IMPORT	11FDEW2	10LBMW1	FRONT	NONE	MODERAT2	
28	UNM 99	DATSUN	SUB/MINI	IMPORT	12FLEW4	9900000	FRONT	NONE	MODERAT2	
29	UNM 99	DATSUN	SUB/MINI	IMPORT	12FLEW4	9900000	REAR	NONE	MODERAT2	
30	NST 044 76	HONDA	SUB/MINI	IMPORT	00TDH03	00RZA03	FRONT	NONE	MINOR 1	
31	NST 051 77	HONDA	SUB/MINI	IMPORT	12FYEW3	12FREN1	FRONT	NONE	MODERAT2	
32	USC 73 36	COLT	SUB/MINI	IMPORT	12FREE2	9900000	FRONT	NONE	MINOR 1	
33	USC 73 37	TOYOTA	SUB/MINI	IMPORT	12FDEW2	9900000	REAR	NONE	MINOR 1	
34	USC 74 4	DATSUN	IMPORTED	SPORTS	01FZEW2	9900000	FRONT	NONE	MINOR 1	
35	SRI 2 033	DATSUN	SUB/MINI	IMPORT	11FYEW1	00TPGN3	FRONT	NONE	MINOR 1	
36	SU 009	DATSUN	SUB/MINI	IMPORT	12FDHA6	9900000	FRONT	NONE	SEVERE 3	
37	SWRI 7147	TOYOTA	COMPACT	02RYAW4	00LYH01	FRONT	LAP	80	FATAL 6	
38	SWRI 7175	TOYOTA	SUB/MINI	IMPORT	08LBAE2	11FDEW2	FRONT	NONE	MINOR 1	
39	SWRI 7176	TOYOTA	COMPACT	11FLMW2	9900000	FRONT	NONE	MODERAT2		
40	SWRI 7176	TOYOTA	COMPACT	11FLMW2	9900000	FRONT	NONE	MODERAT2		
41	SWRI 7246	TOYOTA	SUB/MINI	IMPORT	01FZEW3	9900000	FRONT	NONE	MODERAT2	
42	SWRI 7246	TOYOTA	SUB/MINI	IMPORT	01FZEW3	9900000	FRONT	NONE	SEVERE 3	
43	SWRI 7310	DATSUN	SUB/MINI	IMPORT	11FZEW3	9900000	FRONT	NONE	MINOR 1	
44	SWRI 73 22	TOYOTA	PICKUP	TRUCK	12FZEW3	9900000	FRONT	NONE	CRITICL5	
45	UC 1265D	TOYOTA	SUB/MINI	IMPORT	11FZEW4	9900000	FRONT	NONE	SEVERE 3	
46	UM 776 73	COLT	SUB/MINI	IMPORT	11FDEW1	09LFEW2	FRONT	NONE	MINOR 1	
47	UM 776 73	COLT	SUB/MINI	IMPORT	11FDEW1	09LFEW2	FRONT	NONE	MINOR 1	

CASE#	TEAM CASE #	MAKE	MODEL	CDC-1	CDC-2	POSITION	BELTS	INJURY (AIS)
48	UM 1185 75	COLT	SUB/MINI	IMPORT	01FDEW3	03RZEW1	FRONT	NONE MODERAT2
49	UM 1185 75	COLT	SUB/MINI	IMPORT	01FDEW3	03RZEW1	FRONT	NONE MODERAT2
50	UM 1307 77	821	PICKUP	TRUCK	02RYAN7	9900000	FRONT	NONE SEVERE 3
51	UOK 72 21	TOYOTA	COMPACT		02FDEW4	03RZHW3	FRONT	NONE FATAL 6
52	TOR 013 71	DATSUN	SUB/MINI	IMPORT	12FLEE3	9900000	FRONT	NONE MINOR 1
53	TOR 017 71	MAZDA	SUB/MINI	IMPORT	04RFEE3	03RBEW2	FRONT	NONE MINOR 1
54	TOR028029 72	TOYOTA	SUB/MINI	IMPORT	01FDEW2	9900000	FRONT	NONE MODERAT2
55	TOR 079 77	TOYOTA	SUB/MINI	IMPORT	12FLEW3	9900000	FRONT	NONE MINOR 1
56	TOR 079 77	TOYOTA	SUB/MINI	IMPORT	12FLEW3	9900000	FRONT	NONE MINOR 1
57	UTAH 134-73	TOYOTA	SUB/MINI	IMPORT	12FDEW1	9900000	FRONT	NONE MODERAT2
58	UTAH 198 74	DATSUN	SUB/MINI	IMPORT	10FYAW9	9900000	FRONT	NONE FATAL 6
59	UTAH 198 74	DATSUN	SUB/MINI	IMPORT	10FYAW9	9900000	FRONT	NONE SEVERE 3
60	UOA 047 73	DATSUN	SUB/MINI	IMPORT	12FDLW5	00TYH02	FRONT	NONE UNK SEV
61	UOA 047 73	DATSUN	SUB/MINI	IMPORT	12FDLW5	00TYH02	FRONT	NONE UNK SEV
62	BCR 004 73	TOYOTA	SUB/MINI	IMPORT	12FZEW2	9900000	FRONT	NONE MINOR 1
63	BCR 006 73	MAZDA	PICKUP	TRUCK	12FREE6	9900000	FRONT	NONE MINOR 1
64	BCR 051 76	HONDA	SUB/MINI	IMPORT	10FDEW3	9900000	FRONT	NONE MINOR 1
65	BCR 055 76	DATSUN	SUB/MINI	IMPORT	12FDEW2	9900000	FRONT	NONE MODERAT2
66	UOC 001 76	DATSUN	SUB/MINI	IMPORT	12FDEW2	9900000	FRONT	NONE CRITICL5
67	UOC 001 76	DATSUN	SUB/MINI	IMPORT	12FDEW2	9900000	FRONT	NONE FATAL 6
68	UOC 001 76	TOYOTA	SUB/MINI	IMPORT	11FLEW4	9900000	FRONT	NONE MINOR 1
69	UOC 005 76	HONDA	SUB/MINI	IMPORT	12FDMW4	9900000	FRONT	NONE FATAL 6
70	UOC 005 76	HONDA	SUB/MINI	IMPORT	12FDMW4	9900000	FRONT	NONE MODERAT2
71	UOC 009 77	TOYOTA	PICKUP	TRUCK	00TZHO6	00LYAO2	FRONT	NONE MODERAT2
72	UOC 014 77	DATSUN	IMPORTED	SPORTS	00TPG04	00XDAO3	FRONT BOTH	54 FATAL 6
73	UOC 014 77	DATSUN	IMPORTED	SPORTS	00TPG04	00XDAO3	FRONT	NONE FATAL 6
74	UOC 018 77	TOYOTA	SUB/MINI	IMPORT	00TDG03	00LYAW3	FRONT	NONE SEVERE 3
75	UOM 004 73	TOYOTA	SUB/MINI	IMPORT	10LPAW6	00RDA01	FRONT	NONE MINOR 1
76	UOM 035 75	TOYOTA	SUB/MINI	IMPORT	01FDEW3	9900000	FRONT	NONE CRITICL5
77	UOM 038 75	DATSUN		UNKNOWN	12FDAW6	9900000	FRONT	NONE FATAL 6
78	UOM 045 75	TOYOTA	SUB/MINI	IMPORT	02RZAN3	9900000	FRONT	NONE MINOR 1
79	UOM 045 75	TOYOTA	SUB/MINI	IMPORT	02RZAN3	9900000	FRONT	NONE MINOR 1
80	UOM 058 76	MAZDA	SUB/MINI	IMPORT	09LYAW4	09LZMW2	FRONT	NONE CRITICL5
81	UOM 085 78	DATSUN	SUB/MINI	IMPORT	02RZAW3	09LPMN1	FRONT	NONE MODERAT2
82	UOM 085 78	DATSUN	SUB/MINI	IMPORT	02RZAW3	09LPMN1	REAR	NONE FATAL 6
83	UOS 012 72	DATSUN	SUB/MINI	IMPORT	12FYEW2	9900000	FRONT	NONE MINOR 1
84	UOS 013 72	DATSUN	SUB/MINI	IMPORT	11FREW4	10FYEW2	FRONT	NONE MODERAT2

SUMMARY LIST OF CPIR OCCUPANTS WEAR RESTRAINTS AND CONTACTING THE WINDSHIELD

CASE#	TEAM CASE #	MAKE	MODEL	CDC-1	CDC-2	POSITION	BELTS	INJURY (AIS)
3	4ME49	DATSUN	PICKUP	TRUCK	00TDHO4	12FDEW2	FRONT	LAP 80 MODERAT2
7	DTS 065 72	DATSUN	SUB/MINI	IMPORT	12FDAW7	00RDA01	FRONT	BOTH 88 FATAL 6
22	UNM 17	TOYOTA		COMPACT	11FYEW5	9900000	FRONT	LAP 30 SEVERE 3
37	SWRI 7147	TOYOTA		COMPACT	02RYAW4	00LYHO1	FRONT	LAP 80 FATAL 6
72	UOC 014 77	DATSUN	IMPORTED	SPORTS	00TPG04	00XDAO3	FRONT	BOTH 54 FATAL 6

SUMMARY LIST OF CPIR CASES WITHOUT PRIMARY FRONTAL IMPACT

CASE#	TEAM CASE #	MAKE	MODEL	CDC-1	CDC-2	POSITION	BELTS	INJURY (AIS)
1	AA 132	COLT	SUB/MINI	IMPORT	02RDAW3	00LDA01	FRONT	NONE SERIOUS4
3	4ME49	DATSUN	PICKUP	TRUCK	00TDH04	12FDEW2	FRONT LAP	80 MODERAT2
8	DTS 103 74	TOYOTA	COMPACT		02RYEW5	03RBEW1	FRONT	NONE CRITICL5
15	EPM 024 72	DATSUN	SUB/MINI	IMPORT	02RPEW4	01FDEW1	FRONT	NONE MODERAT2
17	EPM 037 73	DATSUN	SUB/MINI	IMPORT	10LDEW2	9900000	FRONT	NONE MINOR 1
21	UNB 094 77	HONDA	SUB/MINI	IMPORT	00TPG03	12FDLW4	FRONT	NONE MINOR 1
23	UNM 33	DATSUN	UNK TYPE	CAR	04RPMW2	9900000	FRONT	NONE MODERAT2
24	UNM 61	DATSUN	SUB/MINI	IMPORT	02RZEW3	9900000	FRONT	NONE MINOR 1
25	UNM 61	DATSUN	SUB/MINI	IMPORT	02RZEW3	9900000	FRONT	NONE MINOR 1
30	NST 044 76	HONDA	SUB/MINI	IMPORT	00TDH03	00RZA03	FRONT	NONE MINOR 1
37	SWRI 7147	TOYOTA	COMPACT		02RYAW4	00LYH01	FRONT LAP	80 FATAL 6
38	SWRI 7175	TOYOTA	SUB/MINI	IMPORT	08LBAE2	11FDEW2	FRONT	NONE MINOR 1
50	UM 1307 77	821	PICKUP	TRUCK	02RYAN7	9900000	FRONT	NONE SEVERE 3
53	TOR 017 71	MAZDA	SUB/MINI	IMPORT	04RFEE3	03RBEW2	FRONT	NONE MINOR 1
71	UOC 009 77	TOYOTA	PICKUP	TRUCK	00TZH06	00LYA02	FRONT	NONE MODERAT2
72	UOC 014 77	DATSUN	IMPORTED	SPORTS	00TPG04	00XDA03	FRONT BOTH	54 FATAL 6
73	UOC 014 77	DATSUN	IMPORTED	SPORTS	00TPG04	00XDA03	FRONT	NONE FATAL 6
74	UOC 018 77	TOYOTA	SUB/MINI	IMPORT	00TDG03	00LYAW3	FRONT	NONE SEVERE 3
75	UOM 004 73	TOYOTA	SUB/MINI	IMPORT	10LPAW6	00RDA01	FRONT	NONE MINOR 1
78	UOM 045 75	TOYOTA	SUB/MINI	IMPORT	02RZAN3	9900000	FRONT	NONE MINOR 1
79	UOM 045 75	TOYOTA	SUB/MINI	IMPORT	02RZAN3	9900000	FRONT	NONE MINOR 1
80	UOM 058 76	MAZDA	SUB/MINI	IMPORT	09LYAW4	09LZMW2	FRONT	NONE CRITICL5
81	UOM 085 78	DATSUN	SUB/MINI	IMPORT	02RZAW3	09LPMN1	FRONT	NONE MODERAT2
82	UOM 085 78	DATSUN	SUB/MINI	IMPORT	02RZAW3	09LPMN1	REAR	NONE FATAL 6

SUMMARY LIST OF CPIR CASES WITH OVERALL INJURY SEVERITY 3 OR GREATER

CASE#	TEAM CASE #	MAKE	MODEL	CDC-1	CDC-2	POSITION	BELTS	INJURY (AIS)
1	AA 132	COLT	SUB/MINI	IMPORT	02RDAW3	00LDA01	FRONT	NONE SERIOUS4
4	BU 73 05	TOYOTA	SUB/MINI	IMPORT	12FYEW2	9900000	FRONT	NONE CRITICL5
7	DTS 065 72	DATSUN	SUB/MINI	IMPORT	12FDAW7	00RDA01	FRONT	BOTH 88 FATAL 6
8	DTS 103 74	TOYOTA		COMPACT	02RYEW5	03RBEW1	FRONT	NONE CRITICL5
12	MGU 094 75	DATSUN	SUB/MINI	IMPORT	11FDAW9	9900000	FRONT	NONE FATAL 6
13	MGU 094 75	DATSUN	SUB/MINI	IMPORT	11FDAW9	9900000	FRONT	NONE CRITICL5
14	C MI 006	SUBARU	SUB/MINI	IMPORT	01FREW2	03RBEW2	FRONT	NONE SEVERE 3
22	UNM 17	TOYOTA		COMPACT	11FYEW5	9900000	FRONT	LAP 30 SEVERE 3
36	SU 009	DATSUN	SUB/MINI	IMPORT	12FDHA6	9900000	FRONT	NONE SEVERE 3
37	SWRI 7147	TOYOTA		COMPACT	02RYAW4	00LYH01	FRONT	LAP 80 FATAL 6
41	SWRI 7246	TOYOTA	SUB/MINI	IMPORT	01FZEW3	9900000	FRONT	NONE SEVERE 3
44	SWRI 73 22	TOYOTA	PICKUP	TRUCK	12FZEW3	9900000	FRONT	NONE CRITICL5
45	UC 1265D	TOYOTA	SUB/MINI	IMPORT	11FZEW4	9900000	FRONT	NONE SEVERE 3
50	UM 1307 77	821	PICKUP	TRUCK	02RYAN7	9900000	FRONT	NONE SEVERE 3
51	UOK 72 21	TOYOTA		COMPACT	02FDEW4	03RZH3	FRONT	NONE FATAL 6
58	UTAH 198 74	DATSUN	SUB/MINI	IMPORT	10FYAW9	9900000	FRONT	NONE FATAL 6
59	UTAH 198 74	DATSUN	SUB/MINI	IMPORT	10FYAW9	9900000	FRONT	NONE SEVERE 3
66	UOC 001 76	DATSUN	SUB/MINI	IMPORT	12FDEW2	9900000	FRONT	NONE CRITICL5
67	UOC 001 76	DATSUN	SUB/MINI	IMPORT	12FDEW2	9900000	FRONT	NONE FATAL 6
69	UOC 005 76	HONDA	SUB/MINI	IMPORT	12FDMW4	9900000	FRONT	NONE FATAL 6
72	UOC 014 77	DATSUN	IMPORTED	SPORTS	00TPG04	00XDA03	FRONT	BOTH 54 FATAL 6
73	UOC 014 77	DATSUN	IMPORTED	SPORTS	00TPG04	00XDA03	FRONT	NONE FATAL 6
74	UOC 018 77	TOYOTA	SUB/MINI	IMPORT	00TDG03	00LYAW3	FRONT	NONE SEVERE 3
76	UOM 035 75	TOYOTA	SUB/MINI	IMPORT	01FDEW3	9900000	FRONT	NONE CRITICL5
77	UOM 038 75	DATSUN		UNKNOWN	12FDAW6	9900000	FRONT	NONE FATAL 6
80	UOM 058 76	MAZDA	SUB/MINI	IMPORT	09LYAW4	09LZMW2	FRONT	NONE CRITICL5
82	UOM 085 78	DATSUN	SUB/MINI	IMPORT	02RZAW3	09LPMN1	REAR	NONE FATAL 6



JAPANESE CARS IN CPIR FILE WITH WINDSHIELD CONTACTS

CASE# 1

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = AA 132  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = 11  
V9:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 020  
V112:CASE VEH. VIN = 6H23K15999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 02RDAW3  
V155:CASE VEH SECONDARY CDC = 00LDA01  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 24  
V587:OCC. WEIGHT, LBS = 157  
V589:OCC. HEIGHT (INCHES) = 71  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12143699  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 12143699  
V614:HEAD OVERALL INJURY = SEVERE 3  
V615:NECK CONTACT AREAS = 14999999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 1  
V16:TEAM CASE NUMBER = AA 132  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12143699

CASE# 1  
V16:TEAM CASE NUMBER = AA 132  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12143699

CASE# 1  
V16:TEAM CASE NUMBER = AA 132  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12143699

CASE# 1  
V16:TEAM CASE NUMBER = AA 132  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 12143699

CASE# 1  
V16:TEAM CASE NUMBER = AA 132  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V637:BODY REGION = CHEST  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 05123699

CASE# 1  
V16:TEAM CASE NUMBER = AA 132  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V637:BODY REGION = CHEST  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 05123699

CASE# 1  
V16:TEAM CASE NUMBER = AA 132  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SERIOUS4  
V637:BODY REGION = ALL BODY  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 05122636

CASE# 2

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = AA 196  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = 16  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 030  
V112:CASE VEH. VIN = RT83705999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = COMPACT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 01FZEW1  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 09  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 21  
V587:OCC. WEIGHT, LBS = 115  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 2

V16:TEAM CASE NUMBER	= AA 196
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 3

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = 4ME49  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = 02  
V9:YEAR OF COLLISION = 70  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN =  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = PICKUP TRUCK  
V119:CASE VEHICLE MODEL YEAR = 70  
V124:CASE VEH BODY STYLE = TRUCK  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = OOTDHO4  
V155:CASE VEH SECONDARY CDC = 12FDEW2  
V168:FRONT INCHES CRUSH = 11  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 57  
V587:OCC. WEIGHT, LBS = 130  
V589:OCC. HEIGHT (INCHES) = 65  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = LAP 80

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 06091012  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 3  
V16:TEAM CASE NUMBER = 4ME49  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06091012

CASE# 3  
V16:TEAM CASE NUMBER = 4ME49  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06091012



CASE# 4

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = BU 73 05  
V7:MONTH OF COLLISION = MAR  
V8:DAY OF COLLISION = 03  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 038  
V112:CASE VEH. VIN = RA21999999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 04  
V143:CASE VEH PRIMARY CDC = 12FYEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 16  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 21  
V587:OCC. WEIGHT, LBS = 150  
V589:OCC. HEIGHT (INCHES) = 69  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V609:BRAIN CONTACT AREAS = 12989999  
V610:BRAIN OVERALL INJURY = CRITICL5  
V611:FACE CONTACT AREAS = 12549999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = SERIOUS4  
V615:NECK CONTACT AREAS = 12999999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12989999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12989999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12989999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12549999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12549999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12549999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12999999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = NECK  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = RT ARM  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 4  
V16:TEAM CASE NUMBER = BU 73 05  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 5

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = BU 74 04  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = 04  
V9:YEAR OF COLLISION = 74  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 020  
V112:CASE VEH. VIN = 6H41K29999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FREN2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 16  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 43  
V587:OCC. WEIGHT, LBS = 160  
V589:OCC. HEIGHT (INCHES) = 63  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 5  
V16:TEAM CASE NUMBER = BU 74 04  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 6

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = CAL 72 286A  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = 29  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 013  
V112:CASE VEH. VIN = 6H23K29999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FDEW1  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 08  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 115  
V589:OCC. HEIGHT (INCHES) = 67  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 10129999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 6

V16:TEAM CASE NUMBER	= CAL 72 286A
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= PAIN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 10129999

CASE# 7

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = DTS 065 72  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 055  
V112:CASE VEH. VIN = PL51025999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FDAW7  
V155:CASE VEH SECONDARY CDC = OORDA01  
V168:FRONT INCHES CRUSH = 72  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 72  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = BOTH 88

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 70999999  
V610:BRAIN OVERALL INJURY = CRITICL5  
V611:FACE CONTACT AREAS = 70129999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 70129999  
V614:HEAD OVERALL INJURY = MODERAT2  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 7  
V16:TEAM CASE NUMBER = DTS 065 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 70129999

CASE# 7  
V16:TEAM CASE NUMBER = DTS 065 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 70129999

CASE# 7  
V16:TEAM CASE NUMBER = DTS 065 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 70129999

CASE# 7  
V16:TEAM CASE NUMBER = DTS 065 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 70129999

CASE# 8

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = DTS 103 74  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 74  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 057  
V112:CASE VEH. VIN = RT72136999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = COMPACT  
V119:CASE VEHICLE MODEL YEAR = 70  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 02RYEW5  
V155:CASE VEH SECONDARY CDC = 03RBEW1  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 20  
V587:OCC. WEIGHT, LBS = 130  
V589:OCC. HEIGHT (INCHES) = 65  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12109999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 12109999  
V614:HEAD OVERALL INJURY = MODERAT2  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 8  
V16:TEAM CASE NUMBER = DTS 103 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12109999

CASE# 8  
V16:TEAM CASE NUMBER = DTS 103 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12109999

CASE# 8  
V16:TEAM CASE NUMBER = DTS 103 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12109999

CASE# 8  
V16:TEAM CASE NUMBER = DTS 103 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 9

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = MGU 076 74  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 74  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 020  
V112:CASE VEH. VIN = PL51042999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 73  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 04  
V143:CASE VEH PRIMARY CDC = 12FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 10  
V338:WINDSHIELD CRACKED = NO  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 24  
V587:OCC. WEIGHT, LBS = 185  
V589:OCC. HEIGHT (INCHES) = 70  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 9  
V16:TEAM CASE NUMBER = MGU 076 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 10

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = MGU 076 74  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 74  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 020  
V112:CASE VEH. VIN = PL51042999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 73  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 04  
V143:CASE VEH PRIMARY CDC = 12FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 10  
V338:WINDSHIELD CRACKED = NO  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 150  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 10

V16:TEAM CASE NUMBER	= MGU 076 74
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= RT ARM
V644:INJURY TYPE	= ABRASION
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 11

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = MGU 091 75  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 999  
V112:CASE VEH. VIN = PL510999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FLEW2  
V155:CASE VEH SECONDARY CDC = 12LZMS1  
V168:FRONT INCHES CRUSH = 11  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 49  
V587:OCC. WEIGHT, LBS = 200  
V589:OCC. HEIGHT (INCHES) = 74  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12109999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 12109999  
V614:HEAD OVERALL INJURY = MODERAT2  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 11  
V16:TEAM CASE NUMBER = MGU 091 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12109999

CASE# 11  
V16:TEAM CASE NUMBER = MGU 091 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12109999

CASE# 11  
V16:TEAM CASE NUMBER = MGU 091 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12109999

CASE# 11  
V16:TEAM CASE NUMBER = MGU 091 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12109999

CASE# 11  
V16:TEAM CASE NUMBER = MGU 091 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 01545512

CASE# 11  
V16:TEAM CASE NUMBER = MGU 091 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 01545512

CASE# 11  
V16:TEAM CASE NUMBER = MGU 091 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = OTHER  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 01545512

CASE# 12

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = MGU 094 75  
V7:MONTH OF COLLISION = AUG  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 015  
V112:CASE VEH. VIN = HLB210999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 11FDAW9  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 29  
V587:OCC. WEIGHT, LBS = 142  
V589:OCC. HEIGHT (INCHES) = 69  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 12141099  
V610:BRAIN OVERALL INJURY = SERIOUS4  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12141099  
V614:HEAD OVERALL INJURY = SERIOUS4  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 12  
V16:TEAM CASE NUMBER = MGU 094 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12141099

CASE# 12  
V16:TEAM CASE NUMBER = MGU 094 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12141099

CASE# 12  
V16:TEAM CASE NUMBER = MGU 094 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12141099

CASE# 13

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = MGU 094 75  
V7:MONTH OF COLLISION = AUG  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 015  
V112:CASE VEH. VIN = HLB210999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 11FDAW9  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 25  
V587:OCC. WEIGHT, LBS = 130  
V589:OCC. HEIGHT (INCHES) = 61  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V609:BRAIN CONTACT AREAS = 12105414  
V610:BRAIN OVERALL INJURY = SERIOUS4  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12105414  
V614:HEAD OVERALL INJURY = SERIOUS4  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 13  
V16:TEAM CASE NUMBER = MGU 094 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12105414

CASE# 13  
V16:TEAM CASE NUMBER = MGU 094 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12105414

CASE# 13  
V16:TEAM CASE NUMBER = MGU 094 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 12105414

CASE# 14

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = C MI 006  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = 12  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 052  
V112:CASE VEH. VIN = A22L904999999  
V116:CASE VEH. MAKE (ABC) = SUBARU  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 74  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 01FREW2  
V155:CASE VEH SECONDARY CDC = 03RBEW2  
V168:FRONT INCHES CRUSH = 20  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 71  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 12999999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = SEVERE 3  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 14  
V16:TEAM CASE NUMBER = C MI 006  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 14  
V16:TEAM CASE NUMBER = C MI 006  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 12999999

CASE# 14  
V16:TEAM CASE NUMBER = C MI 006  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999



CASE# 15

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = EPM 024 72  
V7:MONTH OF COLLISION = FEB  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN = PL51033999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 02RPEW4  
V155:CASE VEH SECONDARY CDC = 01FDEW1  
V168:FRONT INCHES CRUSH = 06  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 30  
V587:OCC. WEIGHT, LBS = UNK  
V589:OCC. HEIGHT (INCHES) = UNK  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12999999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 54999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 15  
V16:TEAM CASE NUMBER = EPM 024 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 15  
V16:TEAM CASE NUMBER = EPM 024 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 16

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = EPM 034 72  
V7:MONTH OF COLLISION = DEC  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 000  
V112:CASE VEH. VIN = TE27045999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FZEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 20  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 22  
V587:OCC. WEIGHT, LBS = 145  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 06129999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 16

V16:TEAM CASE NUMBER	= EPM 034 72
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 06129999

CASE# 17

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = EPM 037 73  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= OTHR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 030  
V112:CASE VEH. VIN = PL51093999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 10LDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = NO  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = N/A  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 30  
V587:OCC. WEIGHT, LBS = 130  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 14129999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 17

V16:TEAM CASE NUMBER	= EPM 037 73
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= CONTUSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 14129999

CASE# 18

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNB 035 73  
V7:MONTH OF COLLISION = JUN  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 020  
V112:CASE VEH. VIN = PL51030999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FLEW1  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 08  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 26  
V587:OCC. WEIGHT, LBS = 163  
V589:OCC. HEIGHT (INCHES) = 70  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12069999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 18

V16:TEAM CASE NUMBER	= UNB 035 73
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= ABRASION
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12069999



CASE# 19

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNB 091 77  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN = TE03999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 77  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FZEW3  
V155:CASE VEH SECONDARY CDC = 99F0000  
V168:FRONT INCHES CRUSH = 27  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 28  
V587:OCC. WEIGHT, LBS = 110  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12141099  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 14659899  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 19  
V16:TEAM CASE NUMBER = UNB 091 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12141099

CASE# 19  
V16:TEAM CASE NUMBER = UNB 091 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 19  
V16:TEAM CASE NUMBER = UNB 091 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 20

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNB 091 77  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN = TE03999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 77  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FZEW3  
V155:CASE VEH SECONDARY CDC = 99F0000  
V168:FRONT INCHES CRUSH = 27  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 29  
V587:OCC. WEIGHT, LBS = 126  
V589:OCC. HEIGHT (INCHES) = 69  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12149999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 12142299  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 20  
V16:TEAM CASE NUMBER = UNB 091 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12149999

CASE# 20  
V16:TEAM CASE NUMBER = UNB 091 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12149999

CASE# 20  
V16:TEAM CASE NUMBER = UNB 091 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12142299

CASE# 21

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNB 094 77  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 055  
V112:CASE VEH. VIN = SBC9999999  
V116:CASE VEH. MAKE (ABC) = HONDA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = OOTPG03  
V155:CASE VEH SECONDARY CDC = 12FDLW4  
V168:FRONT INCHES CRUSH = 06  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 140  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 21

V16:TEAM CASE NUMBER	= UNB 094 77
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= LF ARM
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12069999

CASE# 22

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 17  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = 27  
V9:YEAR OF COLLISION = 70  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 035  
V112:CASE VEH. VIN =  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = COMPACT  
V119:CASE VEHICLE MODEL YEAR = 69  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 11FYEW5  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 30  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 23  
V587:OCC. WEIGHT, LBS = 115  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = LAP 30

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = SEVERE 3  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 22  
V16:TEAM CASE NUMBER = UNM 17  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 22  
V16:TEAM CASE NUMBER = UNM 17  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 22  
V16:TEAM CASE NUMBER = UNM 17  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 12999999



CASE# 23

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 33  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = 13  
V9:YEAR OF COLLISION = 70  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 012  
V112:CASE VEH. VIN = PL51009999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = UNK TYPE CAR  
V119:CASE VEHICLE MODEL YEAR = 68  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 04RPMW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = NO  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 57  
V587:OCC. WEIGHT, LBS = 140  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 14221299  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 23

V16:TEAM CASE NUMBER	= UNM 33
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MODERAT2
V637:BODY REGION	= FACE
V644:INJURY TYPE	= CONTUSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 14221299

CASE# 24

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 61  
V17:MONTH OF COLLISION = JUL  
V18:DAY OF COLLISION = 08  
V19:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 006  
V112:CASE VEH. VIN = PL51089999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 70  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 02RZEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 80  
V587:OCC. WEIGHT, LBS = 180  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 24

V16:TEAM CASE NUMBER	= UNM 61
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 25

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 61  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = 08  
V9:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 006  
V112:CASE VEH. VIN = PL51089999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 70  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 02RZEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 67  
V587:OCC. WEIGHT, LBS = 140  
V589:OCC. HEIGHT (INCHES) = 62  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 12999999  
V610:BRAIN OVERALL INJURY = MINOR 1  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 25

V16:TEAM CASE NUMBER	= UNM 61
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= BRAIN
V644:INJURY TYPE	= CONCUSSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 26

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 81  
V7:MONTH OF COLLISION = FEB  
V8:DAY OF COLLISION = 11  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 043  
V112:CASE VEH. VIN = 99LB11 999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 01FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 17  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 17  
V587:OCC. WEIGHT, LBS = 185  
V589:OCC. HEIGHT (INCHES) = 74  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12999999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 26  
V16:TEAM CASE NUMBER = UNM 81  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 26  
V16:TEAM CASE NUMBER = UNM 81  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 26  
V16:TEAM CASE NUMBER = UNM 81  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999



CASE# 27

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 94  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = 17  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 032  
V112:CASE VEH. VIN = PL51099999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 11FDEW2  
V155:CASE VEH SECONDARY CDC = 10LBMW1  
V168:FRONT INCHES CRUSH = 13  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 28  
V587:OCC. WEIGHT, LBS = 170  
V589:OCC. HEIGHT (INCHES) = 69  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12099999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 12099999  
V614:HEAD OVERALL INJURY = MODERAT2  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 27  
V16:TEAM CASE NUMBER = UNM 94  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12099999

CASE# 27  
V16:TEAM CASE NUMBER = UNM 94  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12099999

CASE# 27  
V16:TEAM CASE NUMBER = UNM 94  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12099999

CASE# 28

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 99  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = 20  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 028  
V112:CASE VEH. VIN = RL41199999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 67  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 12FLEW4  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 16  
V587:OCC. WEIGHT, LBS = 117  
V589:OCC. HEIGHT (INCHES) = 67  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 28

V16:TEAM CASE NUMBER	= UNM 99
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MODERAT2
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MODERAT2
V646:AREAS CONTACTED	= 12999999

CASE# 29

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UNM 99  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = 20  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 028  
V112:CASE VEH. VIN = RL411999999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 67  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 12FLEW4  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 16  
V587:OCC. WEIGHT, LBS = 108  
V589:OCC. HEIGHT (INCHES) = 62  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12549999  
V610:BRAIN OVERALL INJURY = MINOR 1  
V611:FACE CONTACT AREAS = 54329999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 29  
V16:TEAM CASE NUMBER = UNM 99  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12549999

CASE# 29  
V16:TEAM CASE NUMBER = UNM 99  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12549999

CASE# 30

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = NST 044 76  
V7:MONTH OF COLLISION = SEP  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 055  
V112:CASE VEH. VIN = SBA9999999  
V116:CASE VEH. MAKE (ABC) = HONDA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = OOTDH03  
V155:CASE VEH SECONDARY CDC = OORZA03  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 27  
V587:OCC. WEIGHT, LBS = 127  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 06129999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 30  
V16:TEAM CASE NUMBER = NST 044 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06129999



CASE# 31

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = NST 051 77  
V7:MONTH OF COLLISION = JUN  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 015  
V112:CASE VEH. VIN = SBD5999999  
V116:CASE VEH. MAKE (ABC) = HONDA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 77  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FYEW3  
V155:CASE VEH SECONDARY CDC = 12FREN1  
V168:FRONT INCHES CRUSH = 10  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 21  
V587:OCC. WEIGHT, LBS = 110  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 10120699  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 10120699  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 31  
V16:TEAM CASE NUMBER = NST 051 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 10120699

CASE# 31  
V16:TEAM CASE NUMBER = NST 051 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 10120699

CASE# 32

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = USC 73 36  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = 25  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 015  
V112:CASE VEH. VIN = 6H45K15999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FREE2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 13  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 22  
V587:OCC. WEIGHT, LBS = 130  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 32

V16:TEAM CASE NUMBER = USC 73 36  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 32

V16:TEAM CASE NUMBER = USC 73 36  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = RT ARM  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 33

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = USC 73 37  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = 26  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 025  
V112:CASE VEH. VIN = TA12999999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 73  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 12FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 12  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LYING  
V584:AGE - YEARS = 23  
V587:OCC. WEIGHT, LBS = 135  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 06129999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 98999999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 33  
V16:TEAM CASE NUMBER = USC 73 37  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LYING  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06129999

CASE# 33  
V16:TEAM CASE NUMBER = USC 73 37  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LYING  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06129999

CASE# 34

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = USC 74 4  
V7:MONTH OF COLLISION = MAR  
V8:DAY OF COLLISION = 31  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 014  
V112:CASE VEH. VIN = SPL3119999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = IMPORTED SPORTS  
V119:CASE VEHICLE MODEL YEAR = 69  
V124:CASE VEH BODY STYLE = CONVERT  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 01FZEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 14  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 35  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 71  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 65129999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 34  
V16:TEAM CASE NUMBER = USC 74 4  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 65129999

CASE# 34  
V16:TEAM CASE NUMBER = USC 74 4  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 65129999

CASE# 34  
V16:TEAM CASE NUMBER = USC 74 4  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 34  
V16:TEAM CASE NUMBER = USC 74 4  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999



CASE# 35

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SRI 2 033  
V7:MONTH OF COLLISION = MAR  
V8:DAY OF COLLISION = 26  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 045  
V112:CASE VEH. VIN = PL510 9999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 04  
V143:CASE VEH PRIMARY CDC = 11FYEW1  
V155:CASE VEH SECONDARY CDC = 00TPGN3  
V168:FRONT INCHES CRUSH = 09  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 18  
V587:OCC. WEIGHT, LBS = 124  
V589:OCC. HEIGHT (INCHES) = 65  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 35

V16:TEAM CASE NUMBER	= SRI 2 033
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= CONTUSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 36

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SU 009  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = 31  
V9:YEAR OF COLLISION = 70  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 065  
V112:CASE VEH. VIN = PL510 999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 69  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FDHA6  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 30  
V587:OCC. WEIGHT, LBS = 160  
V589:OCC. HEIGHT (INCHES) = 72  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 09129999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 36  
V16:TEAM CASE NUMBER = SU 009  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 09129999

CASE# 36  
V16:TEAM CASE NUMBER = SU 009  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 09129999

CASE# 37

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 7147  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = 16  
V9:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 055  
V112:CASE VEH. VIN = RT52 999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = COMPACT  
V119:CASE VEHICLE MODEL YEAR = 68  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 02RYAW4  
V155:CASE VEH SECONDARY CDC = 00LYH01  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = UNK  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 125  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = LAP 80

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 31999999  
V610:BRAIN OVERALL INJURY = FATAL 6  
V611:FACE CONTACT AREAS = 05201412  
V612:FACE OVERALL INJURY = SEVERE 3  
V613:HEAD CONTACT AREAS = 31051412  
V614:HEAD OVERALL INJURY = SERIOUS4  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 37  
V16:TEAM CASE NUMBER = SWRI 7147  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 05201412

CASE# 37  
V16:TEAM CASE NUMBER = SWRI 7147  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 05201412

CASE# 37  
V16:TEAM CASE NUMBER = SWRI 7147  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 31051412

CASE# 37  
V16:TEAM CASE NUMBER = SWRI 7147  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 31051412

CASE# 37  
V16:TEAM CASE NUMBER = SWRI 7147  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = SHOULDER  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 05201412

CASE# 37  
V16:TEAM CASE NUMBER = SWRI 7147  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = SHOULDER  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 05201412

CASE# 37

V16:TEAM CASE NUMBER	= SWRI 7147
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= FATAL 6
V637:BODY REGION	= LF ARM
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 05129999

CASE# 38

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 7175  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = 19  
V9:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 015  
V112:CASE VEH. VIN = TE289999999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 08LBAE2  
V155:CASE VEH SECONDARY CDC = 11FDEW2  
V168:FRONT INCHES CRUSH = 13  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 22  
V587:OCC. WEIGHT, LBS = 145  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12069999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 38

V16:TEAM CASE NUMBER	= SWRI 7175
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12069999

CASE# 39

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 7176  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = 25  
V9:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 025  
V112:CASE VEH. VIN = RT62999999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = COMPACT  
V119:CASE VEHICLE MODEL YEAR = 70  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 11FLMW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 19  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 28  
V587:OCC. WEIGHT, LBS = 170  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 09999999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 39  
V16:TEAM CASE NUMBER = SWRI 7176  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 40

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 7176  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = 25  
V9:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 025  
V112:CASE VEH. VIN = RT62999999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = COMPACT  
V119:CASE VEHICLE MODEL YEAR = 70  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 11FLMW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 19  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 13  
V587:OCC. WEIGHT, LBS = 070  
V589:OCC. HEIGHT (INCHES) = 60  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 22999999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 40  
V16:TEAM CASE NUMBER = SWRI 7176  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 40  
V16:TEAM CASE NUMBER = SWRI 7176  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 40  
V16:TEAM CASE NUMBER = SWRI 7176  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 40  
V16:TEAM CASE NUMBER = SWRI 7176  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 40  
V16:TEAM CASE NUMBER = SWRI 7176  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 40  
V16:TEAM CASE NUMBER = SWRI 7176  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 41

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 7246  
V7:MONTH OF COLLISION = SEP  
V8:DAY OF COLLISION = 15  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 010  
V112:CASE VEH. VIN = TE2161S999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 01FZEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 25  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 17  
V587:OCC. WEIGHT, LBS = 135  
V589:OCC. HEIGHT (INCHES) = 67  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 06120509  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 06120509  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 41

V16:TEAM CASE NUMBER = SWRI 7246  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06120509

CASE# 41

V16:TEAM CASE NUMBER = SWRI 7246  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06120509

CASE# 41

V16:TEAM CASE NUMBER = SWRI 7246  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 06120509

CASE# 42

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 7246  
V7:MONTH OF COLLISION = SEP  
V8:DAY OF COLLISION = 15  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 010  
V112:CASE VEH. VIN = TE2161S999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 01FZEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 25  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 17  
V587:OCC. WEIGHT, LBS = 145  
V589:OCC. HEIGHT (INCHES) = 63  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 14122299  
V610:BRAIN OVERALL INJURY = SEVERE 3  
V611:FACE CONTACT AREAS = 14122299  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 42  
V16:TEAM CASE NUMBER = SWRI 7246  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 14122299

CASE# 42  
V16:TEAM CASE NUMBER = SWRI 7246  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 14122299

CASE# 43

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 7310  
V7:MONTH OF COLLISION = AUG  
V8:DAY OF COLLISION = 20  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 020  
V112:CASE VEH. VIN = LB11009999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 11FZEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 23  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 20  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 70  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 65999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 43

V16:TEAM CASE NUMBER	= SWRI 7310
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= FACE
V644:INJURY TYPE	= ABRASION
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 44

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = SWRI 73 22  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = 31  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN = RD22999999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = PICKUP TRUCK  
V119:CASE VEHICLE MODEL YEAR = 73  
V124:CASE VEH BODY STYLE = TRUCK  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FZEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 33  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 37  
V587:OCC. WEIGHT, LBS = 170  
V589:OCC. HEIGHT (INCHES) = 73  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V609:BRAIN CONTACT AREAS = 12359999  
V610:BRAIN OVERALL INJURY = CRITICL5  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 52999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 44

V16:TEAM CASE NUMBER = SWRI 73 22  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 12359999

CASE# 44

V16:TEAM CASE NUMBER = SWRI 73 22  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12359999

CASE# 44

V16:TEAM CASE NUMBER = SWRI 73 22  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 45

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UC 1265D  
V7:MONTH OF COLLISION = UNK  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = UNK  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 045  
V112:CASE VEH. VIN =  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 69  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 11FZEW4  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 30  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 24  
V587:OCC. WEIGHT, LBS = 175  
V589:OCC. HEIGHT (INCHES) = 74  
V590:OCCUPANT SEX = UNK  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 10129999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 45  
V16:TEAM CASE NUMBER = UC 1265D  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 10129999

CASE# 45  
V16:TEAM CASE NUMBER = UC 1265D  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 45  
V16:TEAM CASE NUMBER = UC 1265D  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 46

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UM 776 73  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = 01  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 023  
V112:CASE VEH. VIN = 6L21K25999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 11FDEW1  
V155:CASE VEH SECONDARY CDC = 09LFEW2  
V168:FRONT INCHES CRUSH = 08  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 24  
V587:OCC. WEIGHT, LBS = 160  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 65999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 46

V16:TEAM CASE NUMBER	= UM 776 73
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= LF ARM
V644:INJURY TYPE	= CONTUSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 47

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UM 776 73  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = 01  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 023  
V112:CASE VEH. VIN = 6L21K25999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 11FDEW1  
V155:CASE VEH SECONDARY CDC = 09LFEW2  
V168:FRONT INCHES CRUSH = 08  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 24  
V587:OCC. WEIGHT, LBS = 170  
V589:OCC. HEIGHT (INCHES) = 73  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 12999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 47

V16:TEAM CASE NUMBER = UM 776 73  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 47

V16:TEAM CASE NUMBER = UM 776 73  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 48

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UM 1185 75  
V7:MONTH OF COLLISION = DEC  
V8:DAY OF COLLISION = 14  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 038  
V112:CASE VEH. VIN = 6P23K45999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 74  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 05  
V143:CASE VEH PRIMARY CDC = 01FDEW3  
V155:CASE VEH SECONDARY CDC = 03RZEW1  
V168:FRONT INCHES CRUSH = 30  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 17  
V587:OCC. WEIGHT, LBS = 140  
V589:OCC. HEIGHT (INCHES) = 69  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12069999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 48

V16:TEAM CASE NUMBER	= UM 1185 75
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MODERAT2
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MODERAT2
V646:AREAS CONTACTED	= 12069999

CASE# 49

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UM 1185 75  
V7:MONTH OF COLLISION = DEC  
V8:DAY OF COLLISION = 14  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 038  
V112:CASE VEH. VIN = 6P23K45999999  
V116:CASE VEH. MAKE (ABC) = COLT  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 74  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 05  
V143:CASE VEH PRIMARY CDC = 01FDEW3  
V155:CASE VEH SECONDARY CDC = 03RZEW1  
V168:FRONT INCHES CRUSH = 30  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 17  
V587:OCC. WEIGHT, LBS = 130  
V589:OCC. HEIGHT (INCHES) = 67  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 49

V16:TEAM CASE NUMBER	= UM 1185 75
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MODERAT2
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MODERAT2
V646:AREAS CONTACTED	= 12999999

CASE# 50

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UM 1307 77  
V7:MONTH OF COLLISION = DEC  
V8:DAY OF COLLISION = 24  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 999  
V112:CASE VEH. VIN = SGTASR99999  
V116:CASE VEH. MAKE (ABC) = 821  
V117:CASE VEH. MODEL (DE) = PICKUP TRUCK  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = TRUCK  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 02RYAN7  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 30  
V587:OCC. WEIGHT, LBS = 195  
V589:OCC. HEIGHT (INCHES) = 72  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 10999999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12109999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 50

V16:TEAM CASE NUMBER	= UM 1307 77
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= SEVERE 3
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12109999

CASE# 51

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOK 72 21  
V7:MONTH OF COLLISION = JUN  
V8:DAY OF COLLISION = 06  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 025  
V112:CASE VEH. VIN = RT89004999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = COMPACT  
V119:CASE VEHICLE MODEL YEAR = 73  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 02FDEW4  
V155:CASE VEH SECONDARY CDC = 03RZHW3  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 18  
V587:OCC. WEIGHT, LBS = 125  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12052299  
V612:FACE OVERALL INJURY = SEVERE 3  
V613:HEAD CONTACT AREAS = 12142278  
V614:HEAD OVERALL INJURY = FATAL 6  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 51  
V16:TEAM CASE NUMBER = UOK 72 21  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 12052299

CASE# 51  
V16:TEAM CASE NUMBER = UOK 72 21  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12052299

CASE# 51  
V16:TEAM CASE NUMBER = UOK 72 21  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12052299

CASE# 51  
V16:TEAM CASE NUMBER = UOK 72 21  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12052299

CASE# 51  
V16:TEAM CASE NUMBER = UOK 72 21  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = OTHER  
V645:INJURY SEVERITY = FATAL 6  
V646:AREAS CONTACTED = 12142278

CASE# 52

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = TOR 013 71  
V7:MONTH OF COLLISION = JAN  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 71  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 015  
V112:CASE VEH. VIN = PL51013999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 70  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FLEE3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 24  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 21  
V587:OCC. WEIGHT, LBS = 130  
V589:OCC. HEIGHT (INCHES) = 67  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 52

V16:TEAM CASE NUMBER	= TOR 013 71
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = TOR 017 71  
 V7:MONTH OF COLLISION = SEP  
 V8:DAY OF COLLISION = UNK  
 V9:YEAR OF COLLISION = 71  
 V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 010  
 V112:CASE VEH. VIN = STA1454999999  
 V116:CASE VEH. MAKE (ABC) = MAZDA  
 V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
 V119:CASE VEHICLE MODEL YEAR = 71  
 V124:CASE VEH BODY STYLE = 2-D SED  
 V128:CASE VEH # OF OCCUPANTS = 04  
 V143:CASE VEH PRIMARY CDC = 04RFEE3  
 V155:CASE VEH SECONDARY CDC = 03RBEW2  
 V168:FRONT INCHES CRUSH = 00  
 V338:WINDSHIELD CRACKED = NO  
 V339:WINDSHIELD BROKEN = NO  
 V340:WINDSHIELD OCC. CONTACT = UNK  
 V341:WIND.CR./BR.-OCC.CONT. = N/A  
 V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
 V579:POSITION ON SEAT = RIGHT  
 V584:AGE - YEARS = 19  
 V587:OCC. WEIGHT, LBS = 100  
 V589:OCC. HEIGHT (INCHES) = 64  
 V590:OCCUPANT SEX = FEMALE  
 V599:RESTRAINT SYSTEM USAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
 V609:BRAIN CONTACT AREAS = 99999999  
 V610:BRAIN OVERALL INJURY = NONE 0  
 V611:FACE CONTACT AREAS = 99999999  
 V612:FACE OVERALL INJURY = NONE 0  
 V613:HEAD CONTACT AREAS = 12999999  
 V614:HEAD OVERALL INJURY = MINOR 1  
 V615:NECK CONTACT AREAS = 99999999  
 V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 53

V16:TEAM CASE NUMBER	= TOR 017 71
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= HEAD
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 54

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = TOR02802972  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 035  
V112:CASE VEH. VIN = KE20139999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 01FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 17  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 25  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 74  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12999999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 06999999  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 54

V16:TEAM CASE NUMBER = TOR02802972  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 54

V16:TEAM CASE NUMBER = TOR02802972  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 55

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = TOR 079 77  
V7:MONTH OF COLLISION = FEB  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 025  
V112:CASE VEH. VIN = KE309999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FLEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 24  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 24  
V587:OCC. WEIGHT, LBS = 140  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 55

V16:TEAM CASE NUMBER	= TOR 079 77
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= LF ARM
V644:INJURY TYPE	= CONTUSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12009999

CASE# 56

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = TOR 079 77  
V7:MONTH OF COLLISION = FEB  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 025  
V112:CASE VEH. VIN = KE30999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FLEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 24  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 22  
V587:OCC. WEIGHT, LBS = 118  
V589:OCC. HEIGHT (INCHES) = 65  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 56

V16:TEAM CASE NUMBER	= TOR 079 77
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 57

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UTAH 134-73  
V7:MONTH OF COLLISION = MAR  
V8:DAY OF COLLISION = 28  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 999  
V112:CASE VEH. VIN = TE210999999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FDEW1  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 05  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 119  
V589:OCC. HEIGHT (INCHES) = 69  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12999999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 57

V16:TEAM CASE NUMBER = UTAH 134-73  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 57

V16:TEAM CASE NUMBER = UTAH 134-73  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 58

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UTAH 198 74  
V7:MONTH OF COLLISION = SEP  
V8:DAY OF COLLISION = 09  
V9:YEAR OF COLLISION = 74  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 050  
V112:CASE VEH. VIN = PL51099999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 10FYAW9  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 18  
V587:OCC. WEIGHT, LBS = 105  
V589:OCC. HEIGHT (INCHES) = 62  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 10142112  
V610:BRAIN OVERALL INJURY = FATAL 6  
V611:FACE CONTACT AREAS = 10142112  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 10142112  
V614:HEAD OVERALL INJURY = SERIOUS4  
V615:NECK CONTACT AREAS = 10142112  
V616:NECK OVERALL INJURY = SEVERE 3

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 58  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = FATAL 6  
V646:AREAS CONTACTED = 10142112

CASE# 58  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 10142112

CASE# 58  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 10142112

CASE# 58  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 10142112

CASE# 58  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SERIOUS4  
V646:AREAS CONTACTED = 10142112

CASE# 58  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = NECK  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 10142112

CASE# 59

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UTAH 198 74  
V7:MONTH OF COLLISION = SEP  
V8:DAY OF COLLISION = 09  
V9:YEAR OF COLLISION = 74  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 050  
V112:CASE VEH. VIN = PL51099999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 10FYAW9  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 125  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 12107205  
V610:BRAIN OVERALL INJURY = MINOR 1  
V611:FACE CONTACT AREAS = 12107205  
V612:FACE OVERALL INJURY = SEVERE 3  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 59  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12107205

CASE# 59  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 12107205

CASE# 59  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12107205

CASE# 59  
V16:TEAM CASE NUMBER = UTAH 198 74  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12107205

CASE# 60

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOA 047 73  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 060  
V112:CASE VEH. VIN = PL51099999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FDLW5  
V155:CASE VEH SECONDARY CDC = OOTYH02  
V168:FRONT INCHES CRUSH = 15  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 22  
V587:OCC. WEIGHT, LBS = UNK  
V589:OCC. HEIGHT (INCHES) = UNK  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= UNK SEV  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 09129999  
V612:FACE OVERALL INJURY = UNK SEV  
V613:HEAD CONTACT AREAS = 10129999  
V614:HEAD OVERALL INJURY = UNK SEV  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 61

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOA 047 73  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 060  
V112:CASE VEH. VIN = PL51099999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FDLW5  
V155:CASE VEH SECONDARY CDC = OOTYH02  
V168:FRONT INCHES CRUSH = 15  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 23  
V587:OCC. WEIGHT, LBS = UNK  
V589:OCC. HEIGHT (INCHES) = UNK  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= UNK SEV  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 10129999  
V616:NECK OVERALL INJURY = UNK SEV

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 62

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = BCR 004 73  
V7:MONTH OF COLLISION = MAR  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 020  
V112:CASE VEH. VIN = TE21109999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FZEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 20  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 62  
V587:OCC. WEIGHT, LBS = 127  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 62

V16:TEAM CASE NUMBER	= BCR 004 73
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= FACE
V644:INJURY TYPE	= CONTUSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 63

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = BCR 006 73  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN = BV06119999999  
V116:CASE VEH. MAKE (ABC) = MAZDA  
V117:CASE VEH. MODEL (DE) = PICKUP TRUCK  
V119:CASE VEHICLE MODEL YEAR = 72  
V124:CASE VEH BODY STYLE = TRUCK  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FREE6  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 24  
V587:OCC. WEIGHT, LBS = 150  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 65999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 63

V16:TEAM CASE NUMBER	= BCR 006 73
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= RT ARM
V644:INJURY TYPE	= PAIN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12659999

CASE# 64

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = BCR 051 76  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 999  
V112:CASE VEH. VIN = SBC9999999  
V116:CASE VEH. MAKE (ABC) = HONDA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 10FDEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 17  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 140  
V589:OCC. HEIGHT (INCHES) = 67  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 12989999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 64

V16:TEAM CASE NUMBER	= BCR 051 76
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= NECK
V644:INJURY TYPE	= PAIN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12989999

CASE# 65

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = BCR 055 76  
V17:MONTH OF COLLISION = NOV  
V18:DAY OF COLLISION = UNK  
V19:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 017  
V112:CASE VEH. VIN = HLB2109999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 21  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 23  
V587:OCC. WEIGHT, LBS = 100  
V589:OCC. HEIGHT (INCHES) = 63  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 10061299  
V610:BRAIN OVERALL INJURY = MINOR 1  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 10061299  
V614:HEAD OVERALL INJURY = MINOR 1  
V615:NECK CONTACT AREAS = 98299999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 65  
V16:TEAM CASE NUMBER = BCR 055 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 10061299

CASE# 65  
V16:TEAM CASE NUMBER = BCR 055 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 65  
V16:TEAM CASE NUMBER = BCR 055 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 65  
V16:TEAM CASE NUMBER = BCR 055 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = HEAD  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 10061299

CASE# 66

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 001 76  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 055  
V112:CASE VEH. VIN = JHL710999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 25  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = UNK  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 68  
V587:OCC. WEIGHT, LBS = 175  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 66

V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 66

V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 66

V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12059999

CASE# 67

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 001 76  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 055  
V112:CASE VEH. VIN = JHL710999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FDEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 25  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = UNK  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 67  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 62  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 12059899  
V616:NECK OVERALL INJURY = CRITICL5

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 67  
V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 129999999

CASE# 67  
V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 129999999

CASE# 67  
V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = NECK  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12059899

CASE# 67  
V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = NECK  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12059899

CASE# 67  
V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = RT ARM  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 12059999

CASE# 68

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 001 76  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 050  
V112:CASE VEH. VIN = RA22999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 11FLEW4  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 31  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 22  
V587:OCC. WEIGHT, LBS = 125  
V589:OCC. HEIGHT (INCHES) = 60  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 68

V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 68

V16:TEAM CASE NUMBER = UOC 001 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 69

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 005 76  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 070  
V112:CASE VEH. VIN = SBA4999999  
V116:CASE VEH. MAKE (ABC) = HONDA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FDMW4  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 38  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 21  
V587:OCC. WEIGHT, LBS = 145  
V589:OCC. HEIGHT (INCHES) = 65  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12109999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 69

V16:TEAM CASE NUMBER	= UOC 005 76
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= FATAL 6
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MODERAT2
V646:AREAS CONTACTED	= 12109999

CASE# 70

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 005 76  
V7:MONTH OF COLLISION = JUL  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 070  
V112:CASE VEH. VIN = SBA4999999  
V116:CASE VEH. MAKE (ABC) = HONDA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FDMW4  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 38  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 21  
V587:OCC. WEIGHT, LBS = 165  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12109999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12109999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 70  
V16:TEAM CASE NUMBER = UOC 005 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12109999

CASE# 70  
V16:TEAM CASE NUMBER = UOC 005 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12109999

CASE# 70  
V16:TEAM CASE NUMBER = UOC 005 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12109999

CASE# 70  
V16:TEAM CASE NUMBER = UOC 005 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = SHOULDER  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12149999

CASE# 70  
V16:TEAM CASE NUMBER = UOC 005 76  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 05129999

CASE# 71

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 009 77  
V7:MONTH OF COLLISION = JAN  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 060  
V112:CASE VEH. VIN = RN23999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = PICKUP TRUCK  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = TRUCK  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = OOTZH06  
V155:CASE VEH SECONDARY CDC = OOLYA02  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 18  
V587:OCC. WEIGHT, LBS = 160  
V589:OCC. HEIGHT (INCHES) = 72  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12259999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 12259999  
V616:NECK OVERALL INJURY = MINOR 1

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 71

V16:TEAM CASE NUMBER = UOC 009 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12259999

CASE# 71

V16:TEAM CASE NUMBER = UOC 009 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = NECK  
V644:INJURY TYPE = PAIN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12259999

CASE# 72

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 014 77  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 080  
V112:CASE VEH. VIN = LHLS30999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = IMPORTED SPORTS  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = OOTPG04  
V155:CASE VEH SECONDARY CDC = OOXDA03  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 20  
V587:OCC. WEIGHT, LBS = 160  
V589:OCC. HEIGHT (INCHES) = 75  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = BOTH 54

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 12109999  
V610:BRAIN OVERALL INJURY = CRITICL5  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 72  
V16:TEAM CASE NUMBER = UOC 014 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12109999

CASE# 72  
V16:TEAM CASE NUMBER = UOC 014 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12109999

CASE# 73

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 014 77  
V7:MONTH OF COLLISION = APR  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 080  
V112:CASE VEH. VIN = LHLS30999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = IMPORTED SPORTS  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = OOTPG04  
V155:CASE VEH SECONDARY CDC = OOXDA03  
V168:FRONT INCHES CRUSH = UNK  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 15  
V587:OCC. WEIGHT, LBS = 125  
V589:OCC. HEIGHT (INCHES) = 64  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 12107899  
V610:BRAIN OVERALL INJURY = CRITICL5  
V611:FACE CONTACT AREAS = 99999999  
V612:FACE OVERALL INJURY = NONE 0  
V613:HEAD CONTACT AREAS = 78999999  
V614:HEAD OVERALL INJURY = MODERAT2  
V615:NECK CONTACT AREAS = 78999999  
V616:NECK OVERALL INJURY = SEVERE 3

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 73

V16:TEAM CASE NUMBER = UOC 014 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12107899

CASE# 73

V16:TEAM CASE NUMBER = UOC 014 77  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12107899

CASE# 74

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOC 018 77  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 019  
V112:CASE VEH. VIN = RA299999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 77  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 04  
V143:CASE VEH PRIMARY CDC = OOTDG03  
V155:CASE VEH SECONDARY CDC = OOLYAW3  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 28  
V587:OCC. WEIGHT, LBS = 163  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= SEVERE 3  
V609:BRAIN CONTACT AREAS = 25109999  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 65209999  
V612:FACE OVERALL INJURY = SEVERE 3  
V613:HEAD CONTACT AREAS = 25109999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 74

V16:TEAM CASE NUMBER	= UOC 018 77
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= SEVERE 3
V637:BODY REGION	= RT ARM
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 22141299

CASE# 75

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 004 73  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 73  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 008  
V112:CASE VEH. VIN = TE21066999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 73  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 10LPAW6  
V155:CASE VEH SECONDARY CDC = OORDA01  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = NO  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 17  
V587:OCC. WEIGHT, LBS = 110  
V589:OCC. HEIGHT (INCHES) = 62  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:



CASE# 75

V16:TEAM CASE NUMBER	= UOM 004 73
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 76

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 035 75  
V7:MONTH OF COLLISION = MAY  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 035  
V112:CASE VEH. VIN = TE28526999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 73  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 01FDEW3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 20  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = UNK  
V341:WIND.CR./BR.-OCC.CONT. = UNK  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 56  
V587:OCC. WEIGHT, LBS = 160  
V589:OCC. HEIGHT (INCHES) = 70  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V609:BRAIN CONTACT AREAS = 54129999  
V610:BRAIN OVERALL INJURY = SEVERE 3  
V611:FACE CONTACT AREAS = 54129999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 76  
V16:TEAM CASE NUMBER = UOM 035 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 54129999

CASE# 76  
V16:TEAM CASE NUMBER = UOM 035 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = SEVERE 3  
V646:AREAS CONTACTED = 54129999

CASE# 76  
V16:TEAM CASE NUMBER = UOM 035 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 54129999

CASE# 76  
V16:TEAM CASE NUMBER = UOM 035 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 54129999

CASE# 77

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 038 75  
V7:MONTH OF COLLISION = JUN  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 060  
V112:CASE VEH. VIN = HLB210999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = UNKNOWN  
V119:CASE VEHICLE MODEL YEAR = 74  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 12FDAW6  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 50  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 26  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 10999999  
V614:HEAD OVERALL INJURY = MODERAT2  
V615:NECK CONTACT AREAS = 65299999  
V616:NECK OVERALL INJURY = UNK SEV

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 77  
V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12999999

CASE# 77  
V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 77  
V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 77  
V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 77  
V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = RT ARM  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 77  
V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = RT ARM  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 77

V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 77

V16:TEAM CASE NUMBER = UOM 038 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = LF ARM  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 78

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 045 75  
V7:MONTH OF COLLISION = NOV  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN = TE37999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 04  
V143:CASE VEH PRIMARY CDC = 02RZAN3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 22  
V587:OCC. WEIGHT, LBS = 160  
V589:OCC. HEIGHT (INCHES) = 68  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 78

V16:TEAM CASE NUMBER	= UOM 045 75
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MINOR 1
V637:BODY REGION	= FACE
V644:INJURY TYPE	= CONTUSN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999



CASE# 79

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 045 75  
V7:MONTH OF COLLISION = NOV  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 75  
V59:VEH TO VEH CONFIGURATION= NONE

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 040  
V112:CASE VEH. VIN = TE37999999  
V116:CASE VEH. MAKE (ABC) = TOYOTA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = 2-D H/T  
V128:CASE VEH # OF OCCUPANTS = 04  
V143:CASE VEH PRIMARY CDC = 02RZAN3  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 155  
V589:OCC. HEIGHT (INCHES) = 67  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 79

V16:TEAM CASE NUMBER = UOM 045 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 79

V16:TEAM CASE NUMBER = UOM 045 75  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 80

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 058 76  
V7:MONTH OF COLLISION = JUN  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 76  
V59:VEH TO VEH CONFIGURATION= L

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 026  
V112:CASE VEH. VIN = SS124W999999  
V116:CASE VEH. MAKE (ABC) = MAZDA  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 75  
V124:CASE VEH BODY STYLE = ST WAGON  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 09LYAW4  
V155:CASE VEH SECONDARY CDC = 09LZMW2  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 19  
V587:OCC. WEIGHT, LBS = 115  
V589:OCC. HEIGHT (INCHES) = 65  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= CRITICL5  
V609:BRAIN CONTACT AREAS = 61146532  
V610:BRAIN OVERALL INJURY = CRITICL5  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 80

V16:TEAM CASE NUMBER	= UOM 058 76
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= RIGHT
V600:OVERALL OCC INJ SEVERITY	= CRITICL5
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MINOR 1
V646:AREAS CONTACTED	= 12999999

CASE# 81

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 085 78  
V7:MONTH OF COLLISION = DEC  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 050  
V112:CASE VEH. VIN = PLF10999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 02RZAW3  
V155:CASE VEH SECONDARY CDC = 09LPMN1  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 32  
V587:OCC. WEIGHT, LBS = 190  
V589:OCC. HEIGHT (INCHES) = 66  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 12142178  
V610:BRAIN OVERALL INJURY = MODERAT2  
V611:FACE CONTACT AREAS = 12142178  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 81  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONCUSSN  
V645:INJURY SEVERITY = MODERAT2  
V646:AREAS CONTACTED = 12142178

CASE# 81  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12142178

CASE# 81  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12142178

CASE# 82

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOM 085 78  
V7:MONTH OF COLLISION = DEC  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 77  
V59:VEH TO VEH CONFIGURATION= T

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 050  
V112:CASE VEH. VIN = PLF10999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 76  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 03  
V143:CASE VEH PRIMARY CDC = 02RZAW3  
V155:CASE VEH SECONDARY CDC = 09LPMN1  
V168:FRONT INCHES CRUSH = 00  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 09  
V587:OCC. WEIGHT, LBS = 061  
V589:OCC. HEIGHT (INCHES) = 50  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V609:BRAIN CONTACT AREAS = 12147899  
V610:BRAIN OVERALL INJURY = CRITICL5  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 12147899  
V616:NECK OVERALL INJURY = FATAL 6

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 82  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12147899

CASE# 82  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = BRAIN  
V644:INJURY TYPE = HEMORRHG  
V645:INJURY SEVERITY = CRITICL5  
V646:AREAS CONTACTED = 12147899

CASE# 82  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = FACE  
V644:INJURY TYPE = LACERATN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12999999

CASE# 82  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = NECK  
V644:INJURY TYPE = FRACTURE  
V645:INJURY SEVERITY = FATAL 6  
V646:AREAS CONTACTED = 12147899

CASE# 82  
V16:TEAM CASE NUMBER = UOM 085 78  
V578:SEAT LOCATION = REAR  
V579:POSITION ON SEAT = LEFT  
V600:OVERALL OCC INJ SEVERITY= FATAL 6  
V637:BODY REGION = NECK  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 12147899



CASE# 83

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOS 012 72  
V7:MONTH OF COLLISION = SEP  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= REAR

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 045  
V112:CASE VEH. VIN = PL510 2999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 4-D SED  
V128:CASE VEH # OF OCCUPANTS = 02  
V143:CASE VEH PRIMARY CDC = 12FYEW2  
V155:CASE VEH SECONDARY CDC = 9900000  
V168:FRONT INCHES CRUSH = 12  
V338:WINDSHIELD CRACKED = NO  
V339:WINDSHIELD BROKEN = NO  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = N/A  
V342:WINDSHIELD BOND SEPAR. = NO

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V584:AGE - YEARS = 33  
V587:OCC. WEIGHT, LBS = 140  
V589:OCC. HEIGHT (INCHES) = 65  
V590:OCCUPANT SEX = FEMALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 54129999  
V612:FACE OVERALL INJURY = MINOR 1  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

CASE# 83

V16:TEAM CASE NUMBER = UOS 012 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = CONTUSN  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 54129999

CASE# 83

V16:TEAM CASE NUMBER = UOS 012 72  
V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = RIGHT  
V600:OVERALL OCC INJ SEVERITY= MINOR 1  
V637:BODY REGION = FACE  
V644:INJURY TYPE = ABRASION  
V645:INJURY SEVERITY = MINOR 1  
V646:AREAS CONTACTED = 54129999

CASE# 84

ACCIDENT DESCRIPTION:

V16:TEAM CASE NUMBER = UOS 013 72  
V7:MONTH OF COLLISION = OCT  
V8:DAY OF COLLISION = UNK  
V9:YEAR OF COLLISION = 72  
V59:VEH TO VEH CONFIGURATION= HEAD

VEHICLE DESCRIPTION:

V75:CASE VEH IMPACT SPEED = 065  
V112:CASE VEH. VIN = PL51029999999  
V116:CASE VEH. MAKE (ABC) = DATSUN  
V117:CASE VEH. MODEL (DE) = SUB/MINI IMPORT  
V119:CASE VEHICLE MODEL YEAR = 71  
V124:CASE VEH BODY STYLE = 2-D SED  
V128:CASE VEH # OF OCCUPANTS = 01  
V143:CASE VEH PRIMARY CDC = 11FREW4  
V155:CASE VEH SECONDARY CDC = 10FYEW2  
V168:FRONT INCHES CRUSH = 22  
V338:WINDSHIELD CRACKED = YES  
V339:WINDSHIELD BROKEN = YES  
V340:WINDSHIELD OCC. CONTACT = YES  
V341:WIND.CR./BR.-OCC.CONT. = YES  
V342:WINDSHIELD BOND SEPAR. = YES

OCCUPANT DESCRIPTION:

V578:SEAT LOCATION = FRONT  
V579:POSITION ON SEAT = LEFT  
V584:AGE - YEARS = 21  
V587:OCC. WEIGHT, LBS = 195  
V589:OCC. HEIGHT (INCHES) = 72  
V590:OCCUPANT SEX = MALE  
V599:RESTRAINT SYSTEM USEAGE = NONE

OVERALL OCCUPANT INJURY DESCRIPTION:

V600:OVERALL OCC INJ SEVERITY= MODERAT2  
V609:BRAIN CONTACT AREAS = 99999999  
V610:BRAIN OVERALL INJURY = NONE 0  
V611:FACE CONTACT AREAS = 12999999  
V612:FACE OVERALL INJURY = MODERAT2  
V613:HEAD CONTACT AREAS = 99999999  
V614:HEAD OVERALL INJURY = NONE 0  
V615:NECK CONTACT AREAS = 99999999  
V616:NECK OVERALL INJURY = NONE 0

INDIVIDUAL WINDSHIELD-CAUSED INJURIES:

Cases Read = 84  
Cases Listed= 84

CASE# 84

V16:TEAM CASE NUMBER	= UOS 013 72
V578:SEAT LOCATION	= FRONT
V579:POSITION ON SEAT	= LEFT
V600:OVERALL OCC INJ SEVERITY	= MODERAT2
V637:BODY REGION	= FACE
V644:INJURY TYPE	= LACERATN
V645:INJURY SEVERITY	= MODERAT2
V646:AREAS CONTACTED	= 12999999

Cases Read = 205

Cases Listed= 205